



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23000935/Rvp3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 27/02/2023

ATTN: CYNTHIA ANG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 5381K	Veh. Inspected	SLK 3940S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1206424-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	31/01/2023

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X1 SDRIVE 18I AT	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAHS120505F03445	Colour	BLACK
Odometer	85590 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2023	Inspect Date / Time	31/01/2023 (02:52 PM)
Survey held at	1002 BUKIT MERAH LANE 3 #01-73 SINGAPORE 159719		
Repairer	3A AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**