

ASS. REC. BY:

REF:

7M1/23000954/KN

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/IVY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

W/Csp will check for 2nd party first

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Paints

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Veh No:

SFC 201A Yr Regn: 01, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester c.G. 1995

Colour

M.L. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

58548

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF1PJSK05JG10278F

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / RTM or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

14/1/23

D.O.I.

1/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg;samuelxie@cdge.com.sg

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
LEE PENG CHONG

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	14/01/2023
Vehicle Reg. No.:	SFC201A	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	31/01/2018
Vehicle Colour:	Grey/Silver	Gen Condition:	Good
Engine No:	FB20YC11834	Chassis No:	JF1SJ5KC5JG102787
Odometer:	58548 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18 7 days		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

Not with work
1. B.I, 11 P.m. &
Running After Rain

COST OF CLAIMS	Amount
Parts	11,346.80
Miscellaneous Items	1,251.00
Labour	3,760.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	17,557.80
+ GST 8.00% (S\$)	1,404.62
Nett Amount (S\$)	18,962.42

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jan 2023)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*TAILGATE	Ry 0.00	0.00	*1,072.80 F	✓
2	1		*REAR WINDSCREEN	Shet/Hou 0.00	0.00	*1,188.20 F	✓
3	1		*TAILGATE LOCK ASSY	fu 0.00	0.00	*176.40 F	✓
4	1		*TAILGATE HINGE LH	R 0.00	0.00	*44.00 F	X
5	1		*TAILGATE HINGE RH	R 0.00	0.00	*44.00 F	X
6	1		*TAILGATE BRAKE LIGHT	fu 0.00	0.00	*180.50 F	X
7	1		*TAILGATE HANDLE GARNISH	Bu 0.00	0.00	*217.00 F	✓
8	1		*TAILGATE HANDLE GARNISH LIGHT		0.00	*57.00 F	?
9	1		*TAILGATE WIPER BLADE	fu 0.00	0.00	*46.40 F	X
10	1		*TAILGATE WIPER MOTOR	clis/fu 0.00	0.00	*217.00 F	✓
11	1		*TAILGATE WIPER MOTOR HARNESS		0.00	*280.00 F	?
12	1		*TAILGATE BRAKE LIGHT HARNESS		0.00	*250.00 F	?
13	1		*TAILGATE INNER TRIM	Bu 0.00	0.00	*190.30 F	✓
14	10		*TAILGATE INNER TRIM CLIP	fu 0.00	0.00	*40.00 F	✓
15	1		*REAR WINDSCREEN SEALANT	fu 0	0.00	*40.00 FS	✓
16	1		*TAILGATE LOCK CATCH	R 0.00	0.00	*24.30 F	X
17	1		*REAR BUMPER	Bt/100 0.00	0.00	*540.30 F	✓
18	10		*REAR BUMPER CLIP	fu 0.00	0.00	*39.00 F	✓
19	1		*REAR BUMPER REFLECTOR LH	fu 0.00	0.00	*22.80 F	X
20	1		*REAR BUMPER REFLECTOR RH	fu 0.00	0.00	*22.80 F	X
21	1		*REAR BUMPER RETAINER LH	D/S 0.00	0.00	*16.30 F	✓
22	1		*REAR BUMPER RETAINER RH	D/S 0.00	0.00	*16.30 F	✓
23	1		*REAR BUMPER TOWING COVER LH	fu 0.00	0.00	*14.30 F	X
24	1		*REAR BUMPER UPPER GARNISH	CM 0.00	0.00	*420.00 F	✓
25	1		*TAILGATE MOULDING	fu 0.00	0.00	*64.30 F	✓
26	1		*REAR BUMPER SPONGE		0.00	*-F	?
27	1		*REAR BUMPER REINFORCEMENT	R 0.00	0.00	*296.50 F	✓
28	1		*REAR BUMPER REINFORCEMENT BRACKET LH		0.00	*-F	?
29	1		*REAR BUMPER REINFORCEMENT BRACKET RH		0.00	*-F	?
30	1		*REAR END PANEL		0.00	*288.00 F	?
31	1		*REAR CHROME WORDING SUBARU	fu 0.00	0.00	*72.30 F	✓
32	1		*REAR CHROME WORDING AWD	fu 0.00	0.00	*40.00 F	✓
33	1		*REAR CHROME WORDING FORESTER	fu 0.00	0.00	*65.00 F	✓
34	1		*EXHAUST MUFFLER	R 0.00	0.00	*617.50 F	X
35	1		*TAILLAMP LH	fu 0.00	0.00	*432.00 F	✓
36	1		*TAILLAMP RH	CM 0.00	0.00	*432.00 F	✓
37	1		*REAR SIDE CORNER PANEL LH		0.00	*-F	?
38	1		*REAR SIDE CORNER PANEL RH		0.00	*-F	?
39	1		*REAR AIR DUCT LH	fu 0.00	0.00	*60.30 F	X
40	1		*REAR AIR DUCT RH	fu 0.00	0.00	*60.30 F	X
41	1		*REAR FENDER LH	R 0.00	0.00	*960.00 F	X
42	1		*REAR FENDER RH	R 0.00	0.00	*960.00 F	X
43	1		*REAR FENDER INNER TRIM LH		0.00	*229.60 F	?
44	1		*REAR FENDER INNER TRIM RH		0.00	*229.60 F	?
45	1		*TAILGATE ABSORBER LH	fu 0.00	0.00	*126.50 F	X
46	1		*TAILGATE ABSORBER RH	fu 0.00	0.00	*126.50 F	X
47	1		*TAILGATE INNER TRIM LH		0.00	*23.00 F	?

48	1	*TAILGATE INNER TRIM RH		0.00	0.00	<i>Sm</i>	*23.00 F	X
49	1	*TAILGATE INNER TRIM UPPER		0.00	0.00	<i>Sm</i>	*48.30 F	X
50	1	*FRONT BUMPER	<i>N</i>	<i>Sm</i>	0.00	0.00	*610.60 F	X
51	1	*FRONT BUMPER RETAINER LH		0.00	0.00	<i>Sm</i>	*15.60 F	X
52	1	*FRONT BUMPER RETAINER RH		0.00	0.00	<i>Sm</i>	*15.60 F	X
53	1	*RADIATOR GRILLE		<i>Sm</i>	0.00	0.00	*325.60 F	X
54	1	*FRONT SUBARU LOGO		<i>Sm</i>	0.00	0.00	*65.00 F	X
55	1	*FRONT FOGLAMP COVER RH		<i>Sm</i>	0.00	0.00	*- F	X

F=Franchise part. S=SpcNett.

Total Parts (S\$)

11,346.80

ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items			Amount
1	1	DASH CAMERA (SET)	900.00
2	1	REAR NUMBER PLATE	60.00
3	1	REVERSE SENSOR (2)	280.00
4	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			1,251.00

Sm
Red
short
X 45m
200m

Estimates on Labour

No Particulars

Lab.Type Amount

Paintwork Labour

1	TO PUTTY, SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR FENDER LH/RH, FRONT BUMPER AND AFFECTED AREAS.	New	1,200.00
---	---	-----	----------

1000
700

Labour Items

2	TO REMOVE & REPLACE DASH CAMERA	New	680.00
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00
4	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, TAILLAMP LH/RH & ALL ACCIDENT DAMAGE AREAS. TO REPAIR FRONT BUMPER & AFFECTED AREAS BY THE ACCIDENT.	New	1,500.00
5	TO CUT, WELD REAR END PANEL & REALIGN AFFECTED AREAS.	New	250.00
6	TUFF COAT REAR END PANEL & AFFECTED AREAS.	New	250.00
7	TO DO WHEEL ALIGNMENT.	New	150.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	New	150.00
9	TO TRANSFER & REPLACE WIPER MOTOR ASSY	New	200.00
10	TO DIAGNOSIS & CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	180.00
11	TO REPAIR/ PULLING THE REAR CHASSIS FRAME MEMBER LH & RH	New	250.00

Gross Labour Cost (\$\$) 4,960.00

ComfortDelGro Engineering Pte Ltd/SFC201A/30/01/2023 16:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/01/2023 12:27 (SGT)
Reported by	Both
Date of Accident	14/01/2023 17:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BISHAN FLYOVER
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFC201A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LEE PENG CHONG
NRIC No	SXXXX037Z
Email Address	PCLEE168@YAHOO.COM
Mobile Phone No	(Phone) +65-98174853
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Subaru
Model	Forester
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	GA319162

DRIVER

Name of Driver	LEE PENG CHONG
NRIC No	SXXXX037Z
Date Of Birth	01/12/1962
Occupation	Indoor

- Information provided must be true and accurate. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurer to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report in the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if so desired.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) carrying out and/or dealing with my defective or remedying, to my insurer by me;
- (iii) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (iv) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Registering Centre Personnel

Sketch Plan

Bishan Flyover

⇒ Toward Upper Serangoon/CTE



Towards Lorong Road

SPH Media Building