



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RODERIC YUEN

Ref: CS/INC23000959/Twp3m4

Date: 23/05/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                        |                       |            |
|---------------------|------------------------|-----------------------|------------|
| <b>Insured Veh.</b> | GBF 1060P              | <b>Veh. Inspected</b> | GBK 9803J  |
| <b>Policy No.</b>   |                        | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | MT/1205897-002         | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | HAZALYSA BINTE IBRAHIM | <b>Assign Date</b>    | 31/01/2023 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |          |
|-------------------------|-------------------|---------------------|----------|
| <b>Make &amp; Model</b> | TOYOTA DYNA       | <b>c.c</b>          | 2982     |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2021     |
| <b>Chassis No.</b>      | JTFAT35Y30K216383 | <b>Colour</b>       | SILVER   |
| <b>Odometer</b>         | 83308 KM          | <b>Steering</b>     | IN ORDER |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | NIL      |
| <b>General</b>          | GOOD              |                     |          |

### 3. Conditions of Tyres

|                       | Size      | Make     | Balance |
|-----------------------|-----------|----------|---------|
| <b>R/H Front Tyre</b> | 195/70R15 | YOKOHAMA | 6 mm    |
| <b>L/H Front Tyre</b> | 195/70R15 | YOKOHAMA | 6 mm    |
| <b>R/H Rear Tyre</b>  | 195/70R15 | YOKOHAMA | 6 mm    |
| <b>L/H Rear Tyre</b>  | 195/70R15 | YOKOHAMA | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |   |                            |                         |
|-----------------------|---|----------------------------|-------------------------|
| <b>Accident Date</b>  | 15/01/2023  | <b>Inspect Date / Time</b> | 31/01/2023 ( 05:00 PM ) |
| <b>Survey held at</b> | FORZA AUTOHAUS PTE. LTD.<br>39 WOODLANDS CLOSE #01-34 MEGA@WOODLANDS SINGAPORE 737856 |                            |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**