

ASS. REC BY:

REF:

INC/ CS/INC23000972/Kvp3

Kernach

ASSIGNMENT

File:

Date:

Estimated Cost:

CO/MP/WS/TP RES/LO RES/EVA/INV/MY

To inspect Vehicle No:

at Workshop no:

of

Insured:

SLB 3882Z

Policy No:

Claims No:

MT/1207226-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8150k

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

30/5/23

Lump Sum \$6200 confirmed with Joe (red 9003.22,59%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

30/5/23-typist

Report Format: TP

Lump Sum /+B+: (\$ 6200)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transportation

S - RS - SI

Fuel

Others

Veh No:

SMT 988PE Yr Regn: 11.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Alpha cc 2494

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

90180

T/Radio: Insured / Std / NI / NA

Eng/No:

CA/No:

JTNGF30HX08006982

Gen. Cond: ~~Good~~ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD/Rim or

Tyre Size:

F:

R:

235/50R18

BS/OUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front

R/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

2H/1/23

Rear

R/Bal.

8 mm

L/Bal.

8 mm

D.O.I.

31/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

Not Authorized

1. B.1, 1/1/2023

Date : 30 / 01 / 2023

4 days

ESTIMATE COSTS OF REPAIR

Mr. Lau Chia Ming, Justin

C/o 160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SMT 9899 E - Toyota Alphard 2.5 CVT

Accident date : 27 / 01 / 2023

Quantity	Descriptions	Amount (S\$)	
1	1 pc o/s head lamp	<i>GR</i> \$ 3,080.00	✓
2	1 pc o/s head lamp side garnish	\$ <i>h</i> 140.00	X
3	1 pc front panel	\$ <i>h</i> 378.00	X
4	1 pc front grille with chrome	<i>m3cm</i> 800.50	✓
5	1 pc front bumper fascia	\$ <i>B</i> 1,398.00	✓
6	1 pc front bumper sponge	\$ 98.00	?
7	10 pc front bumper top garnish clip 1 @ 5.60	\$ <i>m</i> 56.00	✓
8	1 pc o/s front bumper side retainer	\$ <i>m</i> 154.00	✓
9	1 pc o/s front bumper fog lamp	\$ 369.00	?
10	1 pc o/s front bumper fog lamp cover.	\$ 140.00	?
11	1 pc o/s front bumper fog lamp bracket	\$ 130.60	?
12	1 pc front bumper lower garnish	\$ <i>h</i> 392.00	X
13	2 pcs front bumper side clips 1 @ 48.20	\$ 96.40	?
14	1 pc o/s front fender	\$ <i>B</i> 1,075.40	✓
15	1 pc o/s front fender inner garnish	\$ <i>cm</i> 308.00	✓
16	10 pcs front bumper clips 1 @ 5.00	\$ <i>m</i> 50.00	✓
17	1 pc wiper tank	\$ 168.00	?
18	1 pc o/s front drive shaft	\$ <i>h</i> 1,820.00	X
19	1 pc o/s front lower arm	\$ <i>h</i> 808.32	X
20	1 pc o/s front kunckle arm	\$ 669.60	?
21	1 pc o/s front kunckle arm bearing	\$ 659.64	?
22	1 pc o/s front shock absorber	\$ <i>h</i> 921.90	X
		\$ 13,713.36	
		\$ 3,428.34	
	Less 25%		
	Balance C/FD	\$ 10,285.02	

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

Balance B/FD (SMT 9899 E)

\$ 10,285.02

14 1 pc o/s front wheel rim
15 1 pc o/s front wheel tyre

Roll/br \$ 1,633.20 sn ✓
\$ *br* 385.00 sn X
\$ 12,303.22

Labour charges
To putty and spray painting
To check wiring
Re-seal anti rust
Remove and refix rear cushion seat, carpet, garnish, etc.
To check wheel alignment

\$ 1,200.00 *500*
\$ 1,000.00 *440*
\$ 160.00 *20*
\$ 200.00 *30*
\$ *na* 180.00 X
\$ 160.00 *60*

Plus : 8% GST

\$ 1,216.26

Grand total

\$ 16,419.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/01/2023 13:52 (SGT)
Reported by Both
Date of Accident 27/01/2023 20:10 (SGT)
Exact Location of Accident 290 Orchard Rd, Singapore 238859
Additional Location Information exit of Paragon Shopping Centre to Bideford Road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT9899E

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Lau Chia Ming Justin
NRIC No SXXXX289B
Email Address lauchiamingjustin@gmail.com
Mobile Phone No (Phone) +65-93670025
Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Toyota
Model Alphard
Variant
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2500

INSURANCE COMPANY

Name of Insurance Company Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number D22MTPV01012783

DRIVER

Name of Driver Lau Chia Ming Justin
NRIC No SXXXX289B
Date Of Birth 08/01/1986
Occupation Indoor

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Actual Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Traffic Police Department for investigation.
- 6 This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

30 JAN 2023

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

