



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: CHARLOTTE CHEW

Ref: CS/INC23000977/Dvp3m4

Date: 21/03/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	FBN 2597J	<b>Veh. Inspected</b>	SMW 1369E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1206807-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	31/01/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI IONIQ	<b>c.c</b>	1580
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	KMHC851CVLU201457	<b>Colour</b>	RED
<b>Odometer</b>	73320 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	MICHELIN	5 mm
<b>L/H Front Tyre</b>	195/65 R15	MICHELIN	5 mm
<b>R/H Rear Tyre</b>	195/65 R15	MICHELIN	5 mm
<b>L/H Rear Tyre</b>	195/65 R15	MICHELIN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	19/01/2023	<b>Inspect Date / Time</b>	31/01/2023 ( 04:00 PM )
<b>Survey held at</b>	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**