



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000979/Uqp3e2 Date: 14/02/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 3761L	Veh. Inspected	SMA 5977P
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS23/0077	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT (A)	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	GK31317744	Colour	BLUE
	Odometer	92319 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R14	WINDFORCE	6 mm
	L/H Front Tyre	185/65 R14	WINDFORCE	6 mm
	R/H Rear Tyre	185/65 R14	WINDFORCE	6 mm
	L/H Rear Tyre	185/65 R14	WINDFORCE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/01/2023	Inspection Date	31/01/2023
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks				
	A)REGISTRATION DATE: 13 JUN 2018 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	