Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA ALTIS


Engine/Chassis No.: MR053REH604575103

Date of accident: 25.01.23

Damaged area: Rear

Not Notheria USm & 5000h Renny After laim 1/2023 ype: TP 6693M 5day

Date: 31/01/2023 Claim Type: TP VRN: SLT6693M



	tems								
S/N	Parts description	12/11/19	QTY		NIT PRICE	1000	AMOUNT		
1		4	1	+	1,813.00	\$	1,813.00	,	
2	Bootlid inner trim	n	1	\$	181.00	\$	181.00	X	
3	Bootlid hinge	K	2	\$	67.00	\$	134.00	X	
4	Bootlid lock	K		\$	259.00	\$	259.00	X	
5	Bootlid lock striker	^	1	\$	115.00	\$	115.00	1	
6	Bootlid key cylinder	_	1	\$	194.00	\$	194.00	X	
7	Bootlid release cable	-	1	\$	153.00	\$	153.00	1 ,	
8	Bootlid weatherstrip	21	1	\$	185.00	\$	185.00	50 11~	9
9	Licence plate lamp	-	2	\$	92.00	\$	184.00	X _	
10	Bootlid chrome garnish 268 Mg c	M	1	\$	317.00	\$	317.00		
11	Bootlid hinge garnish	-	2	\$	49.00	\$	98.00	1	
12	Bootlid "TOYOTA" logo	4	1	\$	61.00	\$	61.00	_	
13	Bootlid "COROLLA" emblem	en	1	\$	47.00	\$	47.00	_	
14	Bootlid "ALTIS" emblem	ken	1	\$	42.00	\$	42.00	_	
15	Bootlid lamp C374.45 Ols CM MIN	7,4	n	\$	574.00	\$	1,148.00		148.0
16	Bootlid lamp sponge seal	L	2	\$	8.00	\$	16.00	X	
17	Rear bumper 581.20 B	n	1	\$	1,188.00	\$	1,188.00		
18	Rear bumper side retainer	11	2	\$	57.00	\$	114.00		
19	Rear bumper reinforcement 379.30	2,	1	\$	576.00	\$	576.00		
20	Rear bumper lower cowling	m	1	\$	288.00	\$	288.00	X	~
21	Taillamp C416.80 MICM Oll 4	7	2	\$	789.00	\$	1,578.00		1.168
22	Taillamp sponge seal	her	2	\$	8.00	\$	16.00		
23	Taillamp panel	K	2	\$	147.00	\$	294.00	*	
24	Taillamp lower bracket	in	2	\$	33.00	\$	66.00	X	
25	End panel 670.10 R	1	1	\$	732.00	\$	732.00		
26	End panel top garnish	/	1	\$	164.00	\$	164.00		
27	Spare tyre floor panel	n	1	\$	895.00	\$	895.00	X	
28	Spare tyre top board	201	1	\$	127.00	\$	127.00		
29	Rear bumper top bracket	in	2	\$	45.00	\$	90.00	X	
30	End panel side bracket	14	2	\$	38.00	\$	76.00	1	
	1				Subtotal	\$	11,151.00	33	
	8				discount		25.00%		
					Total	\$	8,363.25	1	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after apray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

lo.	Parts description		QTY	UN	IT PRICE		AMOUNT
1	Rear licence plate & frame	4	1	\$	55.00	\$	55.00
2	Reverse camera	1	1	\$	350.00	\$	350.00
3	Reverse sensor short		1	\$	280.00	\$	280.00
4	Bootlid inner trim clips ~~	1	10	\$	5.50	\$	55.00
5	Rear bumper clips		10	\$	5.50	\$	55.00
6	Taillamp clips	en	6	\$	5.50	\$	33.00
7	Bootlid lamp clips	~	6	\$	5.50	\$	33.00
3	End panel sealant		1	\$	120.00	\$	120.00
9	End panel top garnish clips		6	\$	5.50	\$	33.00
10	Spare tyre floor panel sealant	~	1	\$	150.00	\$	150.00
1	Sundries	~	1	\$	50.00	\$	50.00
					Total	Ś	1,214.00

abo	Description	Work unit	Δι	mount
lo.		WOLK GILL		illouite
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$	1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$	50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$	100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$	1,200.00
5	To rust proof all affected portions after repair.	0.5	\$	100.00
	The second secon	otal labour	\$	2,850.00

SF0F231U0002 / FALCON-AIR AUTO SERVICES PTE LTD [575721] ENTRY DATE & TIME: 30/01/2023 12:17 (SGT) SUBMITTED BY: Florence Loh

VERSION: 1 (30/01/2023 12:17 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

1001		AT2 1		1345
ΔC^{-1}	11 + 11		$I \leftarrow I \land I$	11-11

Date of Submission	30/01/2023 12:17 (SGT)
Reported, by	Both
Date of Accident	25/01/2023 16:00 (SGT)
Exact Location of Accident	Upper Thomson Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT6693M	
INSURED/POLICYHOLDER		
ls company? Name Of Registered Owner NRIC No Email Address Mobile Phone No Alternative Phone No	No CHEW CHYE HENG SXXXX673C fcloke@hotmail.com.sg (Phone) +65-64511558	
VEHICLE PARTICULARS		

Manufacturer	Toyota
Model	COROLLA ALTIS STANDARD
Variant	
Exact purpose for which vehicle was being used at time of	
accident	-
Are you claiming under your own insurance policy for repair to	
your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG22014744

DRIVER

Name of Driver	- CHEW CHYE HENG
NRIC No.	SXXXX673C
Date Of Birth	16/02/1951
Occupation	Indoor

Date Of Driving Pass	20/03/1981	
Driving experience	41 YEARS AND 10 MONTHS	
Gender	Male	de la constante de la constant
Mobile Number	(Phone) +65-64511558	
Alt. Phone Number		
Email Address	fcloke@hotmail.com.sg	
Address	49 TAGORE AVENUE	
Address complement		
Postcode	787667	
Is the driver the policyholder?	Yes	
If No, Relationship of the Driver with the Insured		
Does Driver Own Other Vehicles?	No	
Vehicle Registration Number of Other Vehicle Owned by Driver		
Insurance Company of Other Vehicle Owned by Driver		
GENERAL INFORMATION OF THE ACCIDENT		
Type of Accident	Collision - Head to Rear	
Weather Conditions	Raining	
Road Surface	Wet	
Nodu Gundos		
OTHER INFORMATION		
Was any foreign vehicle involved in the accident?	No	
Number of vehicles involved in the accident	2	
Was anybody injured in the Accident?	No	
Was any injured conveyed to hospital by ambulance?	- V	
Was any other vehicle or property damaged?	Yes	
Number of Passengers (Including Driver)	1	
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No	
Translator's name		
Translator's ID		
Translator's phone number		
Translator's email		
Original language used in the statement		
DETAILS OF POLICE ACTION		
	N ₁	
Was the accident reported to the police?	No No	
Was notice of intended Prosecution given?	110	
If yes, against whom?		
CIRCUMSTANCES OF ACCIDENT		
REFER TO SKETCH PLAN.		
NOTE: VEHICLE REPAIR AT OWNER W/SHOP - THIAM HENC	TAUH	
ATTACHMENT(S)		
Are accident photos available for attachment?	Yes No	
Was there any video captured by Car Camera?	NO	
DETAILS OF OTHE	ER VEHICLE PROPERTY 1	
Valida Degistration Number	GBL9158H	
Vehicle Registration Number	GDL913011	
Vehicle Manufacturer		
Vehicle Model		
Vehicle Colour		
Vehicle Colour Vehicle Category	Commercial vehicle	
venicle Category		

Name of Driver	QUEK JUN HAO, AMADEUS
	SXXXX510J
Contact Number	-
Address	-
Address complement	_
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

olicyholder's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Cer Personnel

Sketch Plan

UPPER THOMSON ROAD

THOMSON ROAD

THOMSON ROAD

M	y car was in a stationary position at the red traffic june
UH	Upper Thomson Road. It was drizzling. While waiting for th
tr	affic light to turn green. I heard a loud bang and my
g	urged forward. I quickly alighted to inspect. I found this
٧	ehicle bearing no. GBL 9158H had failed to stop in time a
#	nuc collided into the ruar of my car. The driver of GBL 9158
	gave me his driving license and untact number. I'm lodg
	this report to make an insurance claim against fibe 9158H
	This type I make the

Driver's Signature (if driver is not the policyholder) / Date ' & Time

Declaration

VWe declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel





-> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Venicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	673C	
Vehicle No.:	SLT6693M	40.000.000.000.000.000.000.000
Vehicle to be Exported:	No	
Intended Deregistration Date:	30 Jan 2023	
Vehicle Make:	TOYOTA	44444
Vahicle Model:	COROLLA ALTIS STANDARD AUTO	
Primary Colour:	Grey	
Manufacturing Year:	2017	
Engine No.: *	1ZR0A29335	
Chassis No.:	MR053REH604575103	
Maximum Power Output:	96.0 kW (128 bhp)	,
Open Market Value:	\$19,741.00	
Original Registration Date:	06 Nov 2017	
First Registration Date:	06 Nov 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$19,741.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	05 Nov 2027	versioner version
PARF Rebate Amount: Intended COE Rebate Details	\$13,818.00	~~~~
COE Expiry Date:	05 Nov 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	*************
QP Paid:	\$41,617.00	
COE Rebate Amount:	\$19,837.00	
Total Rebate Amount:	\$33,655.00	

The information contained herein is correct as at 30 Jan 2023