



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2301775

INV Date 22/03/2023

Reference CS/EQI23000982/Awp3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 7544Y
Insured Veh. SGK 9033E
Claim No. DM23HO00210
Policy No.
Accident Date 20/01/2023
Inspection Date 01/03/2023

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (8%)	12.80
Grand Total	172.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Ref: CS/EQI23000982/Awp3e2

Date: 22/03/2023

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 9033E	Veh. Inspected	SMS 7544Y
Policy No.		Coverage (\$)	0.00
Claim No.	DM23HO00210	Excess (\$)	0.00
Assign From	JOSEPHINE WONG	Assign Date	30/01/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GK82102615	Colour	BLUE
Odometer	61874 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R17	OTTIMA	6 mm
L/H Front Tyre	205/45 R17	OTTIMA	6 mm
R/H Rear Tyre	205/45 R17	OTTIMA	6 mm
L/H Rear Tyre	205/45 R17	OTTIMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2023	Inspection Date	01/03/2023
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 7544Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,150.60	985.00
2	FRONT BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
1	FRONT HEAD LAMP	CRACKED	2,455.60	2,236.00
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	75.20	-
1	FRONT FENDER	TO REPAIR SEE LABOUR	520.00	-
1	FRONT FENDER EMBLEM	NOT NECESSARY	90.00	-
1	FRONT FENDER INNER COWLING	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-919.24	-644.20
			3,676.96	2,576.80
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
			40.00	20.00
<u>LABOUR</u>				
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		1,000.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	400.00
	TUFF COAT.		100.00	30.00
	WIRING CHECK.		250.00	30.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
			2,450.00	860.00
GRAND TOTAL			6,166.96	3,456.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/EQI23000982/Awp3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/01/2023 15:08 (SGT)
Reported by	Both
Date of Accident	20/01/2023 11:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PREMISES OF BLK 509 BEDOK NORTH STREET 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS7544Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KOH SEE MIN
NRIC No	S8486292D
Email Address	benkoh525@gmail.com
Mobile Phone No	(Phone) +65-81115666
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Policy Number / Cover Note Number	PNPV2022-00000341

DRIVER

Name of Driver	KOH SEE MIN
NRIC No	S8486292D
Date Of Birth	25/05/1984
Occupation	Outdoor

Date Of Driving Pass	26/01/2013
Driving experience	10 YEARS
Gender	Male
Mobile Number	(Phone) +65-81115666
Alt. Phone Number	-
Email Address	benkoh525@gmail.com
Address	APT BLK 63 CHESTNUT AVENUE
Address complement	# 08-14
Postcode	679523
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE ATTACHED POLICE REPORT- T/20230120/7026

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK9033E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for investigation
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes



 Policyholder's Signature : Date & Time




 Driver's Signature (if driver is not the policyholder) : Date & Time

 20/1/23

 Witnessed by Reporting Centre Personnel

Sketch Plan

BIK 509 BIKK NORTH street 3



(A) SMS 7544Y
 (B) SAK 9033E



SINGAPORE
POLICE FORCE



T:20230120/7026

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No T:20230120/7026

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMS7544Y	FWD Singapore Pte. Ltd	PNPV2022-00000341	12/03/2022	11/03/2023

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	KOH SEE MIN		ID No.	S8486292D
Related Vehicle	SMS7544Y (Car)		Contact No.	81115666
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL

Brief Details

ON 20/01/2023 AT ABOUT 0750 HOURS, I PARKED MY VEHICLE STATIONARY AT THE CARPARK OF PREMISES OF BLK 509 BEDOK NORTH STREET 3 AND EVERYTHING WAS INTACT. AT ABOUT 1100 HOURS, I WENT BACK TO MY VEHICLE AND I REALISED THAT MY FRONT PORTION OF MY VEHICLE (A) WAS DAMAGED. I VIEWED BACK MY CCTV FOOTAGE AND REALISED THAT THE FRONT PORTION OF MY VEHICLE (A) WAS CAUSED BY A VEHICLE (B) WHO HIT AND RAN AWAY. I WISH TO STATE THAT IT IS A HIT AND RUN CASE AND NOBODY WAS ONBOARD ON MY VEHICLE

(A) SMS7544Y
(B) SGK9033E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 7544Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 7544Y

RE-INSPECTION

