

Service Request Details

Claim	S3M04I9G
Reference	CS/HSB23001007/Uqp3m4 
Loss Date	21 January 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	25 Jan 2023 10:26:13 AM
Request Date	1 February 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident	FBH1352L
Vehicle	
Registration #	
Make	TPVD
Model	MOTORCYCLE

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP PDF.pdf	Other	Other	do not reply	
 HSB-LKKInvoice-	Invoice	Surveyor/ Assessor	LKK AUTO CONSULTANTS PTE	23 February

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
AC2301098.pdf.pdf		expense	LTD (TP)	2023
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	23 February 2023
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	23 February 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 February 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 February 2023
 FBH 1352L-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 February 2023
 EMAIL FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	2 February 2023
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	1 February 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	31 January 2023
 SHA4751P INSD GIA.pdf.pdf	Reports & Statement	GIA Report	KALE Nagesh	25 January 2023