

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC23001026/Wqp3m4
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	13/02/2023
	ATTN: DAVID PHU	Α		Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLG 7164K	Veh. Inspected		SMP 5607D
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1207770-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		01/02/2023
2. Vehicle Particulars & Condition					
	Make & Model	BMW 216I GRAN TOURER	c.c		1499
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	WBA6V120305N83078	Colour		WHITE
	Odometer	66091 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/50 R17	CONTINENTAL		7 mm
	L/H Front Tyre	225/50 R17	CONTINENTAL		7 mm
	R/H Rear Tyre	225/50 R17	CONTINENTAL		7 mm
	L/H Rear Tyre	225/50 R17	CONTINENTAL		7 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	30/01/2023	Inspect Date / T	ime	01/02/2023 ( 01:00 PM )
	Survey held at	BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 451875			
	Repairer	SHIFTER AUTO GARAGE PTE LTD			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23001026/Wqp3m4

Inspected By

**Asst. Automotive Assessor** 

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser