

(08/11/13)

wet

ASS. REC. BY: Paul

REF:

CS/CTI 2300 1054/RP3

2438

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLZ 7396H

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 112K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT 66K

Rasul finalised final fig \$19023.12, 10 days. (Red \$4936.36, 21%)

Date/Time, File Pass to? : Preli. Report

1) 21/03 Typist : Final Report

Date/Time, File Return to? 2) _____

Report Format : MER-TP

Lump Sum / I.B.I. (\$) 19023.12

Veh No: SLZ 7396H Yr Regn: 2018 / AM

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN Tiguan CLS/R c.c 1395

Colour: WHITE A/C: insured / Std / NI / NA

Sp. Reading: 61244 T/Radio: insured / Std / NI / NA

Eng/No: _____

C/No: NV4222SNZJW848831

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/01/23 D.O.I. 02/02/23

Survey held at VOLKSWAGEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ S + RS _____ SI

Photos _____

Others _____

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) LTD.
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
TINA
ROGALIND JOHN
SA CORPORATION ROAD
#05-10
Singapore 649821

Document no.
Document date 27-01-2023
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2023002497/ 1
Job order date 27-01-2023
Service Advisor Dass Anthonidas
Christopher

License plate SLZ7396H	Model code AD13PY	First registration 14-05-2018	VIN WVGZZZ5NZJW848831	Model Tiguan Comfortline EQP 1.4 TSI 110kW DSG	Mileage 20
---------------------------	----------------------	----------------------------------	--------------------------	--	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
9801B003	B&P WHEEL ALIGNMENT				#6	360.00	388.80
9801B001	R&R RIM & BALANCE				#6	50.00	54.00
5NA821105B	Fender LHS FENDER <i>repair</i>	1	pcs.	816.36	#6	816.36	881.67
5NA854731E 9B9	Wheel Cover Satin Black LHS FENDER WHEEL ARCH <i>sc</i>	1	pcs.	244.63	#6	244.63	264.20
3C0853586	Grommet <i>nee</i>	8	pcs.	1.88	#6	15.04	16.24
5NA831055N	Door LHS FRT DOOR <i>bt</i>	1	pcs.	2,254.08	#6	2,254.08	2,434.41
5NA837701A 5AP D 378500A2	Door Seal Outer Black <i>nee</i> Alu-Lamin.Insulation <i>nee</i> DOOR INSULATOR <i>nee</i>	1	pcs.	267.94	#6	267.94	289.38
N 91203801	Bolt With Polygon Socket <i>nee</i>	2	pcs.	5.71	#6	11.42	12.33
WHT005504	Fill. Hd. Screw <i>nee</i>	2	pcs.	3.12	#6	6.24	6.74
6R0839829D	Rivet <i>nee</i>	3	pcs.	1.27	#6	3.81	4.11
533867910A	Felt Strip <i>?</i>	1	pcs.	24.17	#6	24.17	26.10
5NA854939AFRYP	Cover For Door Satin Blac LHS FRT DOOR LOWER PROTECTOR <i>de</i>	1	pcs.	343.25	#6	343.25	370.71
3C0853586	Grommet <i>nee</i>	8	pcs.	1.88	#6	15.04	16.24
5NA833055L	Door LHS REAR DOOR <i>bt</i>	1	pcs.	3,065.64	#6	3,065.64	3,310.89
5NA839701A 5AP D 378500A2	Door Seal Outer Black <i>nee</i> Alu-Lamin.Insulation <i>nee</i> DOOR INSULATOR <i>nee</i>	1	pcs.	248.04	#6	248.04	267.88
N 91203801	Bolt With Polygon Socket <i>nee</i>	2	pcs.	5.71	#6	11.42	12.33
WHT005504	Fill. Hd. Screw <i>nee</i>	2	pcs.	3.12	#6	6.24	6.74
5G0837732A	Clip <i>nee</i>	2	pcs.	1.56	#6	3.12	3.37
6R0839829D	Rivet <i>nee</i>	3	pcs.	1.27	#6	3.81	4.11
5NA854949AFRYP	Cover For Door Satin Blac LHS REAR DOOR LOWER PROTECTOR <i>sc</i>	1	pcs.	500.95	#6	500.95	541.03
3C0853586	Grommet <i>nee</i>	8	pcs.	1.88	#6	15.04	16.24
5NA854819J 9B9	Wheel Cover Satin Black LHR FENDER WHEEL ARCH <i>sc</i>	1	pcs.	426.03	#6	426.03	460.11
3C0853586	Grommet <i>nee</i>	8	pcs.	1.88	#6	15.04	16.24
5G0010029J	Sticker With Pictogram Fo B- PILLAR AIR BAG STICKER <i>nee</i>	1	pcs.	24.97	#6	24.97	26.97
5NA601025B 8Z8 311601361	Alloy Wheel Diamond Silve <i>sc</i> Rubber Valve <i>nee</i> LABOUR <i>84</i> SPRAY PAINT <i>84</i> TRANSFER DOOR MECHANISM <i>84</i>	1	pcs.	2,855.89	#6	2,855.89	3,084.36
		1	pcs.	3.99	#6	3.99	4.31
		1	pcs.	840.00	#6	840.00	5,443.20
		2	pcs.	800.00	#6	1,600.00	5,184.00
		2	pcs.	840.00	#6	1,680.00	1,814.40

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
 Singapore 159934
 Biz. Reg. No.: 199101494Z
 GST No.: M200985052



Quotation Non binding - Preview

Page 2/2

Company
 CHINA TAIPING INSURANCE (S) PL.
 3 ANSON ROAD
 #18-00 SPRINGLEAF TOWERS
 Singapore 079909

Customer Details:
 Ms.
 FMA
 ROSALIND JOHN
 84 CORPORATION ROAD
 #05-10
 Singapore 649821

Document no.
 Document date 27-01-2023
 Customer no. 5211001170
 Customer GST-ID 200208384E
 Dealer 30001
 Job order number 2023002497/ 1
 Job order date 27-01-2023
 Service Advisor Dass Anthonidas
 Christopher

License plate	Model code	First registration	VIN	Model	Mileage		
SLZ7396H	AD13PY	14-05-2018	WVGZZZ5NZJW848831	Tiguan Comfortline EQP 1.4 TSI 110kW DSG	20		
Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST

CHINA TAIPING DIRECT
 DOA:25/01/2023
 TP VEH NO:SME6337J
 SURVEY BY:

Quotation valid till 03-02-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	1,170.00	22,789.48	8%	1,916.76	23,959.48	25,876.24
Total	1,170.00	22,789.48		1,916.76	23,959.48	25,876.24

Customer

anic
 Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Ram
 Hp 90010068
 10 days
 P/P
 02/02/23 @ 1100
 Resy before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/01/2023 10:57 (SGT)
Reported by	Driver
Date of Accident	25/01/2023 07:10 (SGT)
Exact Location of Accident	Pioneer Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ7396H

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TINA ROSALIND JOHN@KOGILAVANI D/O JOHN
NRIC No	SXXXX243B
Email Address	roshev5211@gmail.com
Mobile Phone No	(Phone) +65-97204177
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Tiguan
Variant	COMFORTLINE 280 TSI EQP
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG22005605

DRIVER

Name of Driver	SHASIKALA J SASHI @SHASIKALA D/O J SASHI
NRIC No	SXXXX438H
Date Of Birth	02/11/1987
Occupation	Indoor

Date Of Driving Pass	20/01/2016
Driving experience	7 YEARS
Gender	Female
Mobile Number	(Phone) +65-87824115
Alt. Phone Number	-
Email Address	roshev5211@gmail.com
Address	90 CORPORATION ROAD #07-20
Address complement	-
Postcode	649824
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicles Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	TRIDEV PRASAD
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 25/01/2023 AROUND 0710HRS I WAS DRIVING VEHICLE A (SLZ7396H) ALONG JURONG WEST STREET 93 ON LANE 1, AS I WAS MOVING ,THERE WAS THIS VEHICLE B(SME6337J) DRIVE OUT FROM YUNAN CRESCENT TO MAJOR ROAD WITHOUT CHECKING THE BLINDSPOT AND UPCOMING VEHICLE AND COLLIDED INTO MY LEFT SIDE PORTION. NOBODY IS INJURED AND NO OTHER VEHICLE IS INVOLVED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME6337J
-----------------------------	----------

Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	LEE MUN CHOON
NRIC No	SXXXX168Z
Contact Number	(Phone) +65-94883742
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims.

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT REPORTING OFFICER

FRO VICKY




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

25/01/2023 1900HRS



Describe Circumstances of the Accident

ON 25/01/2023 AROUND 0710HRS I WAS DRIVING VEHICLE A (SLZ7396H) ALONG JURONG WEST STREET 93 ON LANE 1, AS I WAS MOVING ,THERE WAS THIS VEHICLE B(SME6337J) DRIVE OUT FROM YUNAN CRESCENT TO MAJOR ROAD WITHOUT CHECKING THE BLINDSPOT AND UPCOMING VEHICLE AND COLLIDED INTO MY LEFT SIDE PORTION. NOBODY IS INJURED AND NO OTHER VEHICLE IS INVOLVED

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

FLASH ACCIDENT REPORTING OFFICER
FRO VICKY



Witnessed by Reporting Centre Personnel

25/01/2023 1900HRS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	243B
Vehicle No.:	SLZ7396H
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Feb 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN COMFORTLINE 280 TSI EQP
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CZE546042
Chassis No.:	WVGZZZ5NZJW848831
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$30,357.00
Original Registration Date:	14 May 2018
First Registration Date:	14 May 2018
Transfer Count:	0
Actual ARF Paid:	\$34,500.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2028
PARF Rebate Amount:	\$25,875.00
COE Expiry Date:	13 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$19,698.00
Total Rebate Amount:	\$45,573.00

The information contained herein is correct as at 03 Feb 2023

OK

Volkswagen Tiguan 1.4A TSI Comfortline EQP Panoramic Roof

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)



JACK CARS



Price **\$112,800**

Depreciation ⓘ

\$17,900 /yr
[View models with similar depre](#)

Reg Date

31-May-2018
(5yrs 3mths 27days COE left)

Mileage

109,318 km (23.3k /yr)

Manufactured ⓘ

2017

Road Tax ⓘ

\$624 /yr

Transmission

Auto

Dereg Value ⓘ

\$46,739 as of today (change)

OMV ⓘ

\$30,742

COE ⓘ

\$38,600

ARF ⓘ

\$35,039

Engine Cap

1,395 cc

Power

110.0 kW (147 bhp)

Curb Weight ⓘ

1,498 kg

No. of Owners ⓘ

2