

(08/11/13) wof
ASS. REC. BY: Pam

REF: CS/SMR 2300 1056/Rup3

2956

08-2026/JAN

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SKD 48734
at Workshop m/s WAH HONG
of 42, TON GUN ROAD EAST #01-79
Insured: SMR

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 43K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 31K

Veh No: SKD 48734 Yr Regn: 2011 / QK

Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA JAZZ 1.3 LA c.c. 1339

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 151676 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMG 68509S 239504

Gen. Cond: Good Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16
R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/01/23 D.O.I. 06/02/23

Survey held at WAH HONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

TRANSITORY

) \$ + \$

) PIONEER

) OTHER

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Bonnet <i>bt</i>		551.00	
1	Bonnet lock <i>X</i>		91.00	
1	Bonnet hinge LH/RH @2*\$ <i>X</i>		39.00	
1	Center grille <i>cut</i>		138.00	
1	Center grille logo badge <i>re</i>		25.00	
1	Front bumper <i>de</i>		630.00	
2	Front bumper side retainer LH/RH @\$15 <i>X</i>		30.00	
1	Fr reinforcement <i>?</i>		273.00	
1	Front bumper lower grille <i>?</i>		151.00	
1	Fr towing cover <i>de</i>		17.00	
1	Headlamp LH/RH @2*\$707 <i>?</i>		1414.00	
1	Support panel <i>repair</i>		450.00	
Part Items Total:			3809.00	
			-20% -761.80	
			3047.20	
<u>SPECIAL NETT ITEMS</u>				
1	Front bumper clips <i>re</i>		35.00	<i>35</i>
1	Bonnet insulator clips <i>re</i>		30.00 <i>✓</i>	
1	Coolant <i>X</i>		50.00 <i>X</i>	
1	Fr carplate with cover <i>bt</i>		35.00 <i>✓</i>	
SN Items Total:			150.00	
Total Parts			3197.20	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	600
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove, replace and focus headlamp	60.00 X	
6	Remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	100.00 X	
Labour Total :		2080.00	
TOTAL (PARTS & LABOUR):		5277.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
L/S
06/02/23 @ 1110
Resurvey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 295G

Vehicle Details

Vehicle No.: SKD4873U
Vehicle to be Exported: No
Intended Deregistration Date: 12 Feb 2023
Vehicle Make: HONDA
Vehicle Model: HONDA JAZZ 1.3L A
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: L13Z11039529
Chassis No.: JHMGE68509S239504
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$19,942.00
Original Registration Date: 07 Dec 2011
First Registration Date: 07 Dec 2011
Transfer Count: 2
Actual ARF Paid: \$19,942.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jan 2026
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$19,069.00
COE Rebate Amount: \$11,318.00
Total Rebate Amount: \$11,318.00

Honda Jazz 1.3A L (COE till 06/2026)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$38,800

Depreciation 

\$11,500 /yr

Reg Date

29-Jun-2011

(3yrs 4mths 16days COE left)

Mileage

N.A.

Manufactured 

2009

Road Tax 

\$708 /yr

Transmission

Auto

Dereg Value 

\$15,281 as of today (change)

OMV 

\$19,656

COE 

\$22,636

ARF 

\$19,656

Engine Cap

1,339 cc

Power

73.0 kW (97 bhp)

Curb Weight 

1,090 kg

No. of Owners 

2

Type of Vehicle

Hatchback