

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/SMR 2300 1056/Rcp3

2956

C08-2026/JAN

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKD 48734

at Workshop m/s WAH HONG

of 42, JOH GUNN ROAD EAST #01-79

Insured:

SMR

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

43K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 48734

Yr Regn:

2011 / Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA JAZZ 1.3 LA

C.C. (339

Colour:

GRAY

A/C: Insured / Std / NI / NA

Sp. Reading

151676

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMG 68509S 239504

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKON

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/01/23

D.O.I.

06/02/23

Survey held at

WAH HONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 31K

13/7/2023

Rahul finalised L&B \$3500; 5 days with repairer. (Red 2441.20, 412)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

: Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS, SI

☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

):

Report Format :

TP

Lump Sum / I.B.I: (\$ 3500)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	295G
Vehicle Details	
Vehicle No.:	SKD4873U
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2023
Vehicle Make:	HONDA
Vehicle Model:	HONDA JAZZ 1.3L A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	L13Z11039529
Chassis No.:	JHMGE68509S239504
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$19,942.00
Original Registration Date:	07 Dec 2011
First Registration Date:	07 Dec 2011
Transfer Count:	2
Actual ARF Paid:	\$19,942.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,069.00
COE Rebate Amount:	\$11,502.00
Total Rebate Amount:	\$11,502.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jan 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2023 15:19 (SGT)
Reported by	Both
Date of Accident	21/01/2023 19:21 (SGT)
Exact Location of Accident	Near 22 Dempsey Rd, Singapore 249679
Additional Location Information	DEMPSY ROAD (BEFORE OPEN SPACE CAR PARK)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD4873U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ABDUL RAZAK BIN MOHAMED ABDUL RAHIM
NRIC No	SXXXX295G
Email Address	RAZAK0109@GMAIL.COM
Mobile Phone No	(Phone) +65-91555686
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1318

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Policy Number / Cover Note Number	PNPV2022-00004286

DRIVER

Name of Driver	ABDUL RAZAK BIN MOHAMED ABDUL RAHIM
NRIC No	SXXXX295G
Date Of Birth	28/09/1968
Occupation	Indoor

Date Of Driving Pass	13/03/1995
Driving experience	27 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91555686
Alt. Phone Number	-
Email Address	RAZAK0109@GMAIL.COM
Address	BLK 217 BUKIT BATOK STREET 21 #12-363
Address complement	-
Postcode	650217
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	YAMONA
Gender	Female

PASSENGER 2

Name	HARI
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number	SHB647D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Jenny Ng

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

ON 21/01/2023 @ 1921HRS, I WAS DRIVING MY VEHICLE A (SKD4873U) ALONG DEMPSY RD (OSCP). BEFORE ENTERING THE OPEN SPACE CAR PARK, MY VEHICLE A (SKD4873U) WAS STATIONARY WAITING FOR THE FRONT VEHICLE B (SHB647D) TO TURN IN TO THE OSCP. SUDDENLY VEHICLE B (SHB647D) ENGAGED REVERSED GEAR AND I HONKED AT HIM BUT HE STILL CONTINUE TO REVERSED AND VEHICLE B (SHB647D) REAR PORTION COLLIDED ONTO THE FRONT PORTION OF MY VEHICLE A (SKD4873U). WE THEN EXCHANGED PARTICULARS FOR INSURANCE CLAIM.

[Signature]

Declaration

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Bonnet <i>bt</i>		551.00	
1	Bonnet lock <i>Xnn</i>		91.00	
1	Bonnet hinge LH/RH @2*\$ <i>Xnn</i>		39.00	
1	Center grille <i>cut</i>		138.00	
1	Center grille logo badge <i>re</i>		25.00	
1	Front bumper <i>de</i>		630.00	
2	Front bumper side retainer LH/RH @*\$15 <i>Xnn</i>		30.00	
1	Fr reinforcement <i>?bt</i>		273.00	
1	Front bumper lower grille <i>?Xnn</i>		151.00	
1	Fr towing cover <i>de</i>		17.00	
1	Headlamp LH/RH @2*\$707 <i>?cm</i>		1414.00	
1	Support panel <i>repair</i>		450.00	
Part Items Total:			3809.00	
			-20% -761.80	
			3047.20	
<u>SPECIAL NETT ITEMS</u>				
1	Front bumper clips <i>re</i>		35.00	<i>35</i>
1	Bonnet insulator clips <i>re</i>		30.00	
1	Coolant <i>Xnn</i>		50.00 <i>X</i>	<i>100</i>
1	Fr carplate with cover <i>bt</i>		35.00	
SN Items Total:			150.00	
Total Parts			3197.20	



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

2438.40

100.00

664.00

1160.00

4362.40

20%

3489.92

48-83500

5 days

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	600
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove, replace and focus headlamp	60.00 X ^m	1160
6	Remove and refit aircon condenser, radiator, related pipes and hoses, vaccum and refill aircon gas	100.00 X ^m	
Labour Total :		2080.00	
TOTAL (PARTS & LABOUR):		5277.20	5941.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

5 days

L/S

06/02/23 @ 1110

Resurvey after repair



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SKD4873U HONDA JAZZ 1.3L A

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMEN T
	<u>PARTS (LIST ITEMS)</u>			
1	Condenser <i>bt</i>		830.00	
			<i>664</i>	
			830.00	
			-20% -166.00	
			664.00	
	<u>SPECIAL NETT ITEMS</u>			
	<u>LABOUR</u>			
		Total Parts	664.00	