

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	-9607198-	·R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS	S/AGI23001070/Kwp3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 18	//04/2023	
			Co	ode: A0	Gl	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJQ 4878A	Veh. Inspected	SI	NH 5704L	
	Policy No.	P10800643R00	Coverage (\$)	0.0	00	
	Claim No.	C10019854/CD	Excess (\$)	0.0	00	
	Assign From	MAYBIE CHUA	Assign Date	01	/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL (A)	c.c	14	96	
	Engine No.	HIDDEN	Year of Reg.	20	115	
	Chassis No.	RU11102323	Colour	M	ETALLIC SILVER	
	Odometer	98203 KM	Steering	IN	ORDER	
	Brakes	IN ORDER	Modification	Sī	TANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	В	alance	
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 ו	mm	
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 ו	mm	
	R/H Rear Tyre	215/60 R16	YOKOHAMA	7 :	mm	
	L/H Rear Tyre	215/60 R16	YOKOHAMA	7 ו	mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/01/2023	Inspection Date	02	2/02/2023	
	Survey held at WEI LEE MOTOR WORKS					
		BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)IN ACCORDANC	Estimate Days of Repair				
b. Estimate Days of Nepall						

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: