



Your Ref: 202332004953

Date: 22<sup>nd</sup> March 2023

Our Ref: CS6/AIS23001086/Cqy3m4

**M/s Allianz Insurance Singapore Pte Ltd**  
79 Robinson Road #09-01  
Singapore 068897

Dear Sir / Madam,

**DESKTOP SURVEY OF ACCIDENT VEHICLE SMW 6356J ACCIDENT ON 19/01/2023**

We thank you for your instruction on 02/02/2023.

The following vehicle information was recorded:

|                      |                         |
|----------------------|-------------------------|
| Registration Number  | : SMW 6356J             |
| Make & Model         | : Nissan Sylphy 1.6 CVT |
| Chassis Number       | : MNTBBAB17Z0037574     |
| Year of Registration | : 2020                  |
| Engine Capacity      | : 1598 cc               |

1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.