

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: IBM 13482
 at Workshop m/s BIKERS AVE
 of 1, BIKERS AVE CRECENT #02-58
 Insured: SLN 6823L III
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____


Veh No: FBM 13482 Yr Regn: 2017 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: YAMAHA C2D300A XMAX 300 c.c. 292
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp. Reading: 54676 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MH3SH081000013038
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-15
 R: 150/70-15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 20/01/23 D.O.I. 02/02/23
 Survey held at BIKERS AVE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S
 The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: 15K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lim Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 12K</u>
	<u>ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K-4K) / 4 days</u>
3/2/23	Submit PRS

Date/Time, File Pass to? ☐ : Prell. Report ☐ : Final Report

1) Date/Time, File Return to?

2) 3/2/23-typist

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : Interview (\$ _____) ☐ : Tech. Invs (\$ _____) ☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	603J
Vehicle Details	
Vehicle No.:	FBM1348Z
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Feb 2023
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	H336E0014735
Chassis No.:	MH35H081000013038
Maximum Power Output:	-
Open Market Value:	\$3,870.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	3
Actual ARF Paid:	\$581.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,001.00
COE Rebate Amount:	\$2,679.00
Total Rebate Amount:	\$2,679.00

The information contained herein is correct as at 02 Feb 2023

Yamaha Xmax 300

Listing Type

Free Ad

Brand

Yamaha

Model

Yamaha Xmax 300

Engine Capacity

292cc

Classification

Class 2A

Registration Date

27/09/2017

COE Expiry Date

26/09/2027

(4yrs 7mths 24days COE left)

Mileage

72061km

No. of owners

1

Type of Vehicle

Scooters

SGD \$15000