

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	9607198-1	₹	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile		
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS	/AGI23001153/Acy3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ite: 17/	07/2023	
			Co	de: AG	il	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SNH 7373U	Veh. Inspected	GB	E 3883Z	
	Policy No.	P10797312R00	Coverage (\$)	0.0	0	
	Claim No.	C10020260/CD	Excess (\$)	0.0	0	
	Assign From	MAYBIE CHUA	Assign Date	02/	02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	SUZUKI EVERY	c.c	658	3	
	Engine No.	HIDDEN	Year of Reg.	201	18	
	Chassis No.	DA17V820955	Colour	WH	HITE	
	Odometer	86977 KM	Steering	IN	ORDER	
	Brakes	IN ORDER	Modification	NIL	_	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Ва	lance	
	R/H Front Tyre	175/65 R14	YOKOHAMA	6 m	nm	
	L/H Front Tyre	175/65 R14	YOKOHAMA	6 m	nm	
	R/H Rear Tyre	175/65 R14	YOKOHAMA	6 m	nm	
	L/H Rear Tyre	175/65 R14	YOKOHAMA	6 m	nm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/02/2023	Inspection Date	03/	02/2023	
	Survey held at	FONG MOTORS				
		1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	DJIN ACCORDANC	Estimate Days of Repair				
Latiniate Days of Nepall						

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: