

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |  |                 |      |                   |  |
|---|---|--|-----------------|------|-------------------|--|
|   | EQ INSURANCE C  | OMPANY LTD                               | Re              | ef:  | CS/EQI23001154/y3 |  |
|   | 5 MAXWELL ROAD<br>#17-00 TOWER BL<br>MND COMPLEXSI  | OCK                                      | Da              | ate: | 03/02/2023        |  |
|   |   |  | Co              | ode: | EQI               |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |   |  |                 |      |                   |  |
|   | Insured Veh.  | GBA 4556H                                | Veh. Inspected  |      | SMS 3871D         |  |
|   | Policy No.  |  | Coverage (\$)   |      | 0.00              |  |
|   | Claim No.   | DM23HO00234/JT                           | Excess (\$)     |      | 0.00              |  |
|   | Assign From   | JAIME TAY                                | Assign Date     |      | 03/02/2023        |  |
| 2. Vehicle Particulars & Condition                                |   |  |                 |      |                   |  |
|   | Make & Model  |  | c.c             |      | 0                 |  |
|   | Engine No.  | HIDDEN                                   | Year of Reg.    |      |                   |  |
|   | Chassis No.   | Colour                                   |                 |      |                   |  |
|   | Odometer -  |  | Steering        |      |                   |  |
|   | Brakes  | Modification                             |                 |      |                   |  |
|   | General   |  |                 |      |                   |  |
| 3. Conditions of Tyres  |   |  |                 |      |                   |  |
|   |   | Size                                     | Make            |      | Balance           |  |
|   | R/H Front Tyre  |  |                 |      | mm                |  |
|   | L/H Front Tyre  |  |                 |      | mm                |  |
|   | R/H Rear Tyre   |  |                 |      | mm                |  |
|   | L/H Rear Tyre   |  |                 |      | mm                |  |
| 4.  | Description of Damages  |  |                 |      |                   |  |
| _   |   |  |                 |      |                   |  |
| 5.  | T   | General Information                      |                 |      |                   |  |
|   | Accident Date   | 30/01/2023                               | Inspection Date |      |                   |  |
|   | Survey held at  | TAN CHONG MOTOR SALES PTE LTD            |                 |      |                   |  |
|   |   | 913 BUKIT TIMAH ROAD<br>SINGAPORE 589623 |                 |      |                   |  |
| 5a. Remarks   |   |  |                 |      |                   |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |      |                   |  |