



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23001164/Uvy3e2 Date: 03/03/2023  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMT 6260S	Veh. Inspected	SMF 4980J
Policy No.		Coverage (\$)	0.00
Claim No.	C10020298 /JL	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	03/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA HRV DX (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMRU1810JX200720	Colour	RED
Odometer	64342 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR, O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	02/02/2023	Inspection Date	03/02/2023
Survey held at	CONVERGENCE AUTOMOTIVE PTE LTD 39 WOODLANDS CLOSE, #01-24, MEGA@WOODLANDS SINGAPORE 737856		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	