

09/11/23

Smy

REF:

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC33324 Yr Regn: 1/2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or _____

Make: hyundai ioniq cc 1.580

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 438317 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Kmh 1851 W/KV 1340501

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD / R/m, or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 17/1/23 D.O.I. 18/1/23 430pm

Survey held at comfast

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Date/Time: 18.01.2023 14:37

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5666468

JC NO 305542952

COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SHC3332L	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 17.01.2023 17:00
	YR OF MANU 01.02.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU134059	COMPLETION DATE/TIME:

JUNT CARD NO.


JOB DESCRIPTION

Accident Date: 17.01.2023
NATURE: 3P 17.01.2023

China Taiping → GZ 7291K

'NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHC3332L-TP



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC3332L LIMITS

Vehicle No.: SHC3332L

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard