

ASS. REC. BY:

REF:

AU/ 2300120311kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 774k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.0.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: Smk 7270D Regn: 04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: 85612 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH0841CMKU893072

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Avro 205/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 24/1/23

Survey held at

Des. of Damages: 015 Rear / Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/2 Bernard said to survey tomorrow.
will see CIA over.

24/2 11 Lm @ 1300k Cahw 315/23

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Transportation

S - RS. \$

Paints

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel : 6471 5111
 Email : claims@cartimes.com.sg

*Not Notified
 Resurvey Repair
 4 days
 11 Sep @ 1300h*

VEHICLE NO: SMK7270D
 CHASSIS NO: KMHD841CMKU893702

MODEL: HYUNDAI AVANTE

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
REAR FENDER	R \$ 2,150.00 X
REAR FENDER INNER SHIELD RHS	Sm \$ 110.00 X
REAR DOOR RHS	R \$ 2,250.00 X
SIDE SKIRT RHS	R \$ 450.00 X
REAR WHEEL HUB RHS <i>454</i>	R \$ 1,550.00 ✓
REAR WHEEL HUB BEARING	R \$ 250.00 ✓
REAR ABSORBER RHS	Sm \$ 320.00 X
REAR AXLE	Sm \$ 1,250.00 X
	\$ 8,330.00
	20% \$ 1,666.00
	\$ 6,664.00
<u>SPECIAL NETT ITEMS</u>	
REAR RIM RHS 15"	\$ <i>nu</i> 250.00 ✓
REAR FENDER INNER SHIELD CLIPS 1 SET	\$ <i>nu</i> 60.00 X
Total	\$ 310.00
TOTAL PARTS	\$ 6,974.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00 <i>200</i>
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00 <i>800</i>
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00 <i>150</i>
4	To provide anti-rust treatment on affected areas	\$ <i>na</i> 100.00 <i>X</i>
5	Dignostic Check	\$ <i>na</i> 100.00 <i>X</i>
Labour Total :		\$ 3,500.00
TOTAL (PARTS & LABOUR):		\$ 10,474.00