

ASS. REC. BY:

REF:

Asm / 23 001218/kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of 01-34 39 Miss C Woodley

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GAR 44066

Yr Regn:

101 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia 1025cc

c.c

2097

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

160227

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNCSTX 762-G7096921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

F: Triangle 195R15X8

R: Corda 155R12X8(1)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

88

mm

L/Bal.

9

mm

L/Bal.

88

mm

D.O.A.

3/2/23

D.O.I.

7/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21 Aug 8 1900h

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ - RS. \$

) F. m/s

) Other

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

**FORZA AUTOHAUS PTE LTD**

39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS
SINGAPORE 737856
TEL: 62781889 EMAIL: ENQUIRY@FORZAAUTO.SG
CO./GST REG: 201833292C

HONG RUI CONSTRUCTION PTE LTD
Contact No. : 96443443

ESTIMATE

Code : E23020005
Date In : 06/02/2023
Vehicle No. : GBF4406G KIA
Model : KIA , K2500 6M
Chassis No. : KNCSJX76LG7096921

Parts and Labour Assessment

Description	Qty	Unit Price	Amount
-------------	-----	------------	--------

Parts & Services

REAR TAILLAMP L/R <i>0224.00</i>	2.00	312.40	<i>CR</i> 624.80 ✓
REAR TAILLAMP PANEL L/R <i>0258.70</i>	2.00	292.10	<i>R</i> 584.20 ✓

Subtotal Before Discount S\$ 1,209.00

10.00% Discount S\$ 120.90

Subtotal S\$ 1,088.10

REAR REVERSE SENSOR SET	1.00	250.00	<i>Ref 2000</i> 250.00 ✓
-------------------------	------	--------	--------------------------

REAR CARRIER No.PLATE SET	1.00	35.00	<i>Ref</i> 35.00 ✓
---------------------------	------	-------	--------------------

REAR STEP BAR	1.00	350.00	<i>R</i> 350.00 ✓
---------------	------	--------	-------------------

Subtotal S\$ 635.00

Parts & Services Total S\$ 1,723.10

Labour

TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	1.00	0.00	0.00
---	------	------	------

TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,000.00	1,000.00 <i>4500</i>
--	------	----------	----------------------

TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,000.00	1,000.00 <i>5000</i>
--	------	----------	----------------------

Subtotal S\$ 2,000.00

Labour Total S\$ 2,000.00

*Not Authorized
11pm @ 1900h
during After Rain
3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **Parts & Services Total S\$**

Date: **Labour Total S\$**

Grand Total S\$

1,723.10

2,000.00

3,723.10