


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMP 8273M
at Workshop m/s Volkswagen
of 17, Twp Ave 9
Insured: AIS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: TBA
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: 94k
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT



Veh No: SMP 8273M Yr Regn: 2019 / OCT
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Golf 1.4 T-1.6c 1395
Colour: BLUE A/C: Insured / Std / NI / NA
Sp. Reading: 33487 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVN222AN ZKW2218482
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: -
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 03/02/23 D.O.I. 06/02/23
Survey held at Volkswagen
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Frt
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
REPAIR LIMIT - 56K

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS, SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

Report Format : _____

Lump Sum / I.B.I. / \$ _____

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/3

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
OH
CHIA-AN, MARCUS
10B EAST COAST AVENUE
SINGAPORE 459182

Document no.
Document date 06-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003264/ 1
Job order date 04-02-2023
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMP8273M	BQ13HZC0	17-10-2019	VWVZZZAUZKW218482	Golf Comfortline 1.4 I TSI 92kW DSG	30,065

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	200.00	216.00
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	360.00	388.80
9801B001	TO ALIGN LED HEADLIGHT				#6	100.00	108.00
9801B003	B&P WHEEL ALIGNMENT				#6	300.00	324.00
9801B001	R&R RIM & BALANCE				#6	50.00	54.00
5G0807217FNGRU	Cover For Bumper Primed de	1	pcs.	1,452.18	28.00%	1,045.57	1,129.22
5G0919493L	Sensor Bracket	1	pcs.	15.49	28.00%	11.15	12.04
5G0919494G	Sensor Bracket	1	pcs.	15.49	28.00%	11.15	12.04
5G0919493J	Sensor Bracket	2	pcs.	14.85	28.00%	21.38	23.09
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	28.00%	60.94	65.82
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	28.00%	53.55	57.83
5G0807049B	Guide Piece	1	pcs.	37.13	28.00%	26.73	28.87
5G2941773	BUMPER SIDE BRACKET LH				#6	2,074.48	2,240.44
3C0973737	Led Headlight LH	1	pcs.	2,881.22	28.00%	15.83	17.10
5G0821105B	Flat Contact Housing With H/LAMP WIRE HOUSING	1	pcs.	21.99	28.00%	489.47	528.63
5G0821135C	Fender LH	1	pcs.	679.82	28.00%	31.69	34.23
5G0805911AJ	Cross Support	1	pcs.	44.01	28.00%	92.64	100.05
5G0805969P	LHS FENDER BRACKET	1	pcs.	128.67	28.00%	206.72	224.88
5G2857507DN9B9	Wheelhouse Liner	1	pcs.	128.67	28.00%	92.64	100.05
5G0857537E GRU	LHS FENDER LINER (LOWER)	1	pcs.	206.72	28.00%	148.84	160.75
5G0857521A	Wheelhouse Liner	1	pcs.	206.72	28.00%	148.84	160.75
5G4831055AS	LHS FENDER LINER (UPPER)	1	pcs.	206.72	28.00%	148.84	160.75
5G4837651B	Rear View Mirror Housing	1	pcs.	738.54	28.00%	531.75	574.29
D 378500A2	Mirror Cap Primed	1	pcs.	188.52	28.00%	135.73	146.59
8K0831401D	Mirror Glass	1	pcs.	208.51	28.00%	150.13	162.14
8K0831401D	Door	1	pcs.	2,556.24	28.00%	1,840.49	1,987.73
N 91203801	LHS FRT DOOR	1	pcs.	132.02	28.00%	95.05	102.65
N 91205602	Door Seal	1	pcs.	43.66	28.00%	31.44	33.96
533867910A	Alu-Lamin. Insulation	1	pcs.	43.66	28.00%	31.44	33.96
	DOOR INSULATION	1	pcs.	43.66	28.00%	31.44	33.96
	Door Hinge	1	pcs.	128.56	28.00%	92.56	99.96
	DOOR HINGE (UPPER)	1	pcs.	128.56	28.00%	92.56	99.96
	Door Hinge	1	pcs.	128.56	28.00%	92.56	99.96
	DOOR HINGE (LOWER)	1	pcs.	128.56	28.00%	92.56	99.96
	Bolt With Polygon Socket	2	pcs.	5.71	28.00%	8.22	8.88
	Hex Bolt With Internal To	4	pcs.	4.13	28.00%	11.89	12.84
	Woofer	1	pcs.	93.38	28.00%	67.23	72.61
	LHS FRT DOOR SPEAKER	1	pcs.	93.38	28.00%	67.23	72.61
	Pop-Rivet	8	pcs.	0.61	28.00%	3.51	3.79
	Fill. Hd. Screw	2	pcs.	3.12	28.00%	4.49	4.85
	Felt Strip	1	pcs.	24.17	28.00%	17.40	18.79

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/3

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
OH
CHIA-AN, MARCUS
10B EAST COAST AVENUE
SINGAPORE 459182

Document no.
Document date 06-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003264/ 1
Job order date 04-02-2023
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMP8273M	BQ13HZC0	17-10-2019	WVWZZZAUZKW218482	Golf Comfortline 1.4 I TSI 92kW DSG	30,065

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
7L6868243	Clip	6	pcs.	1.77	28.00% #6	7.65	8.26
5G4809835	Sectional Part-Pillar A/B	1	pcs.	1,675.13	28.00% #6	1,206.09	1,302.58
D 506KD1A4	2k-Insert Foam	1	pcs.	176.68	28.00% #6	127.21	137.39
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	73.44	28.00% #6	52.88	57.11
D 007500A2	Zinc Spray	1	pcs.	75.80	28.00% #6	54.58	58.95
D 180003M2	2k-Body Adhesive	1	pcs.	509.24	28.00% #6	366.65	395.98
VWLM6114	UNDERSEAL	1	pcs.	15.50	28.00% #6	11.16	12.05
5G0071303B	1 Set Sill Panel Moulding SCUFF PLATE INNER	1	pcs.	202.64	28.00% #6	145.90	157.57
5E0601025AJHA7	Alloy Wheel	1	pcs.	2,579.76	28.00% #6	1,857.43	2,006.02
311601361	Rubber Valve	1	pcs.	3.99	28.00% #6	2.87	3.10
	LABOUR	6	pcs.	560.00	#6 2240	3,280.00	3,628.80
	SPRAY PAINT	6	pcs.	530.00	#6 2385	3,180.00	3,434.40
	TRANSFER DOOR MECHANISM	1	pcs.	560.00	#6 280	560.00	604.80
	R&R FRT INTERIOR CARPET	1	pcs.	560.00	#6 280	560.00	604.80
	ALLIANZ OD						
	D.O.A: 03-02-2023						
	EXCESS: \$600						
	SURVEY BY:						

Quotation valid till 11-02-2023

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	1,010.00	18,658.29	4,277.16	8%	1,573.46	4,277.16	19,668.29	21,241.75
Total	1,010.00	18,658.29	4,277.16		1,573.46	4,277.16	19,668.29	21,241.75

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	715E
Vehicle No.:	SMP8273M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI CL
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CZCC06899
Chassis No.:	WVWZZZAUZKW218482
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,699.00
Original Registration Date:	17 Oct 2019
First Registration Date:	17 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$19,699.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2029
PARF Rebate Amount:	\$14,774.00
COE Expiry Date:	16 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$22,749.00
Total Rebate Amount:	\$37,523.00

The information contained herein is correct as at 07 Feb 2023

OK

Volkswagen Golf 1.4A TSI Comfortline

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$94,800		
Depreciation ⓘ	\$12,690 /yr View models with similar depre	Reg Date	17-Oct-2019 (6yrs 8mths 9days COE left)
Mileage	57,800 km (17.4k /yr)	Manufactured ⓘ	2019
Road Tax ⓘ	\$624 /yr	Transmission	Auto
Dereg Value ⓘ	\$37,532 as of today (change)	OMV ⓘ	\$19,700
COE ⓘ	\$34,001	ARF ⓘ	\$19,700
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight ⓘ	1,270 kg	No. of Owners ⓘ	2
Type of Vehicle	Hatchback		



Commercial
Vehicles

Quotation
Non binding - Preview

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
OH
CHIA-AN, MARCUS
10B EAST COAST AVENUE
SINGAPORE 459182

Page 3/3
Document no.
Document date 06-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003264/ 1
Job order date 04-02-2023
Service Advisor YEN MEI WONG

License plate SMP8273M	Model code BQ13HZC0	First registration 17-10-2019	VIN WVWZZZAUZKW218482	Model Golf Comfortline 1.4 I TSI 92kW DSG	Mileage 30,065
---------------------------	------------------------	----------------------------------	--------------------------	--	-------------------

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passal
Hp 9001w18
10 days
06/02/23 @ 1430
P/P
EXCESS: TBA
Resurvey
Resurvey before paint