* serv	
ASS, REG. BY:	
	ASSIGNMENT 100 A 100 A 100 A
rom: Date:	Veh No: SMF 8019 J Yr Regn: 2018, NOV
stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
D / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
n spect Vehicle No:	Make: Mazdu 3 c.c 1496
Workshop m/s	Colour Grey, A/C: Insured / Std / NI / NA
	Sp.Reading / 08864 . T/Radio: Insured / Std / NI / NA
sured: GBJ 1656A	Eng/No:
olicy No.	C/No: JM68N22A8K0249059
laims No. CDMCG23000168	Gen. Cond. Good Fair / Poor / Burnt
um Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205/60 R16-
(Policy Condition)	R: 205/60R16.
Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Certification
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : You	es or No R/Bal. Ob mm R/Bal. Ob mm
GIA / PR Seen: Consistent?: Y	
Est. Repairs: days Res.: Yo	es or No D.O.A. 11/1/2023 D.O.I. 27 03/23
% 3 Val.: Ye	es or No Survey held at Modern
CA / REV / REP. / 24 HRS	Des. of Damages : Frt   Rear   O/S   N/S   U/C   Rooftop or
Date: Person Contacted:	Vehicle: IN / OUT  The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	•
20/4/23 Adrian confirmed LS	\$3400 (red 5521.76, 61%)
MV:	
Nett:	
71011	
	2790
Date/Time, File Pass to? : Preli. Report	t Days Of Repair: 4
; Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
2) 25/4/23-typist	Add Fee: Site Insp (\$ )_S+RS_SI
	: Interview (\$) Photos
Report Formet : TP	: Tech. Invs (\$) Others
1 mm	. 161-1 16