

Vehicle Damage Assessment Report for [SLE3622S]

Estimate Created: 07/02/2023 02:02 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 20/02/2023 10:08 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	INDIA	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SLE3622S	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	101,981.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- - Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Insurlogic 5 (20/02/2023 10:07)

Amount : \$9,156.45

Check: \$486.90

Repair Duration: 8 days

Labor

Labor Rate	S\$ 50 / Hour	General Labor Subtotal	0.00
		Paint Labor Subtotal	0.00
		Labor Subtotal	0.00

Summary

Repair Cost	0.00
Discount(0.00 %)	(0.00)
	0.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	0.00