

ASS. REC. BY:

REF: TY /

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$57k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 08 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 36225Yr Regn: 07, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy AltisC.C. 1598Colour: M. D. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 101981

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH104554966Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Devanti

Front

Rear

R/Bal. 5 mmR/Bal. 4 mmL/Bal. 5 mmL/Bal. 4 mmD.O.A. 22/1/23D.O.I. 8/2/2023

Survey held at _____

Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

S - RS. \$

Fees

Others

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg;samuelxie@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
Policy No: D20MFL0000326_02
Vehicle Reg. No.: **SLE3622S**
Driver Age/Info:
TP Injury Involved? NO
Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD

Ref. No:
Date of Loss: 22/01/2023
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC
CVT (A)
Vehicle Colour: GREY
Engine No: 1ZRX587166
Odometer: 0 KM

Vehicle Reg. Date: 19/07/2016

Chassis No: MR053REH104554966

Paint Type:
List Item Discount: 25.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 8 ✓

Not Withheld
1/1 Rm &
Repair After Rain

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS

	Amount
Parts	9,325.27
Miscellaneous Items	161.00
Labour	3,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,016.27
+ GST 8.00% (S\$)	1,041.30
Nett Amount (S\$)	14,057.57

This claim is handled by: OI SUN PINGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

PAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 04 Feb 2023)

Parts: 143 **TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SLE3622S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1			*FRONT BUMPER	25.00	0.00	CM *639.80 FL	✓
1			*FRONT CHROME GRILLE	25.00	0.00	CM *770.80 FL	✓
1			*FRONT LOWER GRILLE	25.00	0.00	SM *94.40 FL	X
1			*LH HEADLAMP	my CM 25.00	0.00	*885.80 FL	✓
1			*RH HEADLAMP	25.00	0.00	*885.80 FL	✓
1			*FRONT BUMPER LH RETAIER	25.00	0.00	Diy *102.60 FL	✓
1			*FRONT BUMPER RH RETAINER	25.00	0.00	Diy *102.60 FL	✓
1			*FRONT SUPPORT PANEL	25.00	0.00	R *1,364.00 FL	X
1			*FRONT BONNET	25.00	0.00	Ry *107.60 FL	✓
1			*FRONT BONNET LOCK	25.00	0.00	R *162.20 FL	X
1			*REAR BOORLID	25.00	0.00	Ry *947.10 FL	✓
1			*REAR BOOTLID LH HINGE	25.00	0.00	R *83.90 FL	X
1			*REAR BOOTLID RH HINGE	25.00	0.00	R *83.90 FL	X
1			*REAR BOOTLID INSULATOR	25.00	0.00	R *437.30 FL	X
1			*REAR BOOT WHEATHERSTRIP	25.00	0.00	*211.10 FL	?
1			*REAR BOOTLID LOCK	25.00	0.00	Diy *480.20 FL	✓
1			*REAR BOOTLID CHROME MOULDING	25.00	0.00	*292.50 FL	?
1			*REAR BOOTLID TOYOTA EMBLEM	25.00	0.00	RM *79.70 FL	✓
1			*REAR BOOT LID COROLLA EMBLEM	25.00	0.00	RM *81.50 FL	✓
1			*REAR VOOTLID ALTIS EMBLEM	25.00	0.00	RM *91.60 FL	✓
1			*REAR BOOTLID LH LAMP	25.00	0.00	CRA *244.60 FL	✓
1			*REAR BOOTLID RH LAMP	25.00	0.00	CM *244.60 FL	✓
1			*LH TAILLAMP	25.00	0.00	CM *456.10 FL	✓
1			*RH TAILLAMP	25.00	0.00	CM *456.10 FL	✓
1			*LH TAILLAMP CLIP	25.00	0.00	RM *6.50 FL	✓
1			*RH TAILLAMP CLIP	25.00	0.00	RM *6.50 FL	✓
1			*LH TAILLAMP BRACKET	25.00	0.00	*72.80 FL	?
1			*RH TAILLAMP BRACKET	25.00	0.00	*72.80 FL	?
1			*REAR BUMPER	25.00	0.00	Ry *669.10 FL	✓
1			*REAR BUMPER LH REFLECTOR	25.00	0.00	SM *72.70 FL	X
1			*REAR BUMPER RH REFLECTOR	25.00	0.00	SM *72.70 FL	X
1			*REAR BUMPER LH RETAINER	25.00	0.00	Diy *131.80 FL	✓
1			*REAR BUMPER RH RETAINER	25.00	0.00	Diy *131.80 FL	✓
1			*REAR LH FENDER INNER TRIM	25.00	0.00	SM *396.40 FL	X
1			*REAR RH FENDER INNER TRIM	25.00	0.00	SM *396.40 FL	X
1			*REAR END PANEL	25.00	0.00	Ry *808.00 FL	✓
1			*REAR END PANEL GARNISH	25.00	0.00	Diy *290.40 FL	✓

e part. L=ListItemDisc.

Sub Total (\$)	12,433.70
- List Item Discount on L Items (\$)	3,108.43
Total Parts (\$)	9,325.27

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	1 FRONT BUMPER CLIPS	50.00 ✓
2	1 REAR BOOTLID CLIPS	50.00 ✓
3	1 RER BUMPER CLIPS	50.00 ✓
4	1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)		161.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	600.00 400l
2	To putty & respray on Front damage parts.	New	600.00 400l
3	To knock & straighten on accident area, to remove & refit Rear damage parts.	New	1,200.00 800l
4	To putty & respray on Rear damage parts.	New	1,000.00 800l
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	New	80.00 ✓
6	To check wiring, focus headlamp & install reverse sensor.	New	50.00 ✓
Gross Labour Cost (S\$)			3,530.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	775H
Vehicle Details	
Vehicle No.:	SLE3622S
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRX587166
Chassis No.:	MR053REH104554966
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	19 Jul 2016
First Registration Date:	19 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2026
PARF Rebate Amount:	\$11,688.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$16,280.00
Total Rebate Amount:	\$27,968.00

Information contained herein is correct as at 01 Feb 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/01/2023 13:17 (SGT)
Reported by	Driver
Date of Accident	22/01/2023 20:30 (SGT)
Exact Location of Accident	Lebuhraya Utara-Selatan, Taman Kulai Jaya, Kulai, Johor, Malaysia
Additional Location Information	TOWARDS SINGAPORE
Country/State of Loss	Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE3622S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORTDELGRO RENT A CAR PTE LTD
Company Reg No	1XXXXX775H
Email Address	dannying@cdgrentacar.com.sg
Mobile Phone No	(Phone) +65-91228803
Alternative Phone No	(Office) +65-68820888

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D20MFL0000326_02

DRIVER

Name of Driver	KHOO GUAN TONG
NRIC No	SXXXX580H
Date Of Birth	06/11/1985

IMPORTANT NOTICE**SKETCH PLAN**

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (Collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

**FLASH ACCIDENT
REPORTING OFFICER**

FRO LATIFF

Policyholder's Signature / Date &
TimeDriver's Signature (if driver is not the policyholder) / Date
& Time 23/01/2023 1730hrsWitnessed by Reporting Centre
Personnel**Sketch Plan**

A - SLE3622S
B - WYX3193
C - VY1140
D - VJM224



NORTH SOUTH HIGHWAY
JOHOR