

COMFORTDELGRO ENGINEERING



ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305544154
Date : 04/02/23

FINALIZATION FORM

To : LKK Fax :
Attn : Mr Naz
Vehicle Reg No. : SHC1356G 30.01.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: III -- GBJ2487P
 2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost \$0.00
 - (c) Lumpsum Repair (if applicable)
 - Total for Lumpsum repair cost after Less: 20% \$1,450.00
 - Final Lumpsum Repair cost \$1,450.00
 3. Estimated normal period for repairs: 2 working days.
 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
 5. Thank you for your assistance. We confirm the estimates and finalized amount
- Signature :  Signature : 
Name : Ms. Loke YY Name : Naz LKK
Tel : 62148355 Date : 20/2/2023
Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$26.75 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Loke Wei Yiang
1

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	30/01/2023
Vehicle Reg. No.:	SHC1356G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 (A)	Vehicle Reg. Date:	07/09/2017
Vehicle Colour:	BLUE		
Engine No:	2ZRS063155	Chassis No:	JTDKB3FU503563946
Odometer:	511934 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,830.07
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,661.07
+ GST 8.00% (S\$)	212.89
Nett Amount (S\$)	2,873.96

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC1356G/30/01/2023 15:05	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PANEL SUB ASSY RR DOOR RH	DID ✓ 25.00	0.00	*1,258.30 FL
2	1		*REAR DOOR POWER WINDOW REGULATOR RH	SVC X 25.00	0.00	*941.80 FL
3	1		*REAR DOOR COMFORT APPS LOGO RH	NEL ✓ 0.00	0.00	*80.00 F
4	1		*RENEW ADVERTISEMENT STICKER	NEL ✓ 0.00	0.00	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,380.10
- List Item Discount on L Items (S\$)	550.03
Total Parts (S\$)	1,830.07

ComfortDelGro Engineering Pte Ltd/SHC1356G/30/01/2023 15:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

3.50

480.00

2 SPRAY PAINTING CHARGE

New

2.50

300.00

3 TRANSFER OF DOOR

New

50

120.00

Gross Labour Cost (S\$)

820.00

ComfortDelGro Engineering Pte Ltd/SHC1356G/30/01/2023 15:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKK

31/1/2023 1600

LIS

2 DAYS

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: