

(08/11/13) wef

ASS - REC. BY: JSK

REF:

CC4/LPC 23001266/Rpa3

2986

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFD 11692at Workshop m/s BORROW MOTORof 2 PRINCE CLEST

Insured:

LPC2

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

111K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFD 11692Yr Regn: 2020 10CTType: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS STN c.c. 1598

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

32062

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR2BE3BE800011048Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/02/23

D.O.I.

08/03/23

Survey held at

BORROWDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 67K

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$))



ehcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

UKK

ESTIMATE

Account Details		Account No.	Customer Details					
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Choo Chwee Har 501 Sembawang Road #04-07 Singapore 757706 Mobile: 92766269					
		Document No.						
		0						
		Document Date						
		06/02/2023						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	ZRE210R	GEXGPZ C1	29/10/2020	SFD1169Z	0	20051	SFD1169Z	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2BE3BE800011048		1ZR0F65453	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI TP INS: TP VEH:YP4570P DATE OF ACC:03.02.2023						50 100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR						198.00
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST						134.64
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						198.00
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS						792 1584.00
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS						656 1312.00
1		SPC507-12005 17 BACK SENSOR (1D4, SILVER METAL			1.00	190.00		190.00
2		S52159-0Z961 COVER, RR BUMPER L/C			1.00	639.80		639.80
3		S52161-0K040 PIECE, RR BUMPER			10.00	4.90		49.00
4		S52023-02240 REINFORCEMENT SUB-AS			1.00	399.90		399.90
UKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
Customer's Signature					Charge Summary			
Signature: _____					Total 4,805.34			
Date: _____					GST 8.00% 384.43			
Please acknowledge receipt of vehicle					Less 0.00			
					Amount Due 5,189.77			

Customer Copy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 298E

Vehicle Details

Vehicle No.: SFD1169Z

Vehicle to be Exported: No

Intended Deregistration Date: 09 Mar 2023

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS STANDARD (AUTO)(2WD)

Primary Colour: White

Manufacturing Year: 2020

Engine No.: 1ZR0F65453

Chassis No.: MR2BE3BE800011048

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$19,615.00

Original Registration Date: 29 Oct 2020

First Registration Date: 29 Oct 2020

Transfer Count: 0

Actual ARF Paid: \$19,615.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Oct 2030

PARF Rebate Amount: \$14,711.00

Intended COE Rebate Details

COE Expiry Date: 28 Oct 2030

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,334.00

COE Rebate Amount: \$28,502.00

Total Rebate Amount: \$43,213.00

Toyota Corolla Altis 1.6A Standard

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)

Price **\$111,800** [Get Pre-approved Loan.](#)

Depreciation [?](#) **\$13,480 /yr** [View models with similar depre](#) **Reg Date** **01-Oct-2020**
(7yrs 6mths 21days COE left)

Mileage **75,000 km (30.8k /yr)** **Manufactured** [?](#) **2020**

Road Tax [?](#) **\$742 /yr** **Transmission** **Auto**

Dereg Value [?](#) **\$43,848 as of today (change)** **OMV** [?](#) **\$19,615**

COE [?](#) **\$38,504** **ARF** [?](#) **\$19,615**

Engine Cap **1,598 cc** **Power** **96.0 kW (128 bhp)**

Curb Weight [?](#) **1,315 kg** **No. of Owners** [?](#) **2**

Type of Vehicle **Mid-Sized Sedan**