

REC BY: T. J. M.

REF:

CS/ TM/ 2300/ 271/ TUGS.

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SHD7160J Yr Regn: 2011 NOV
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai 140. C.C. 1685
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 86 2361 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: UMHLB41UM H4096364
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: 205/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO, or Westerlake
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.L. 6/2/23
Survey held at Comfort Lodge
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or
Rear N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Insp (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	

Map/Fortuit: _____
Lump Sum / 24 HRS: _____


am: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5812124 JC NO 305544763

OMER	REGN NO: SHD7160J	MILEAGE
COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. 7010045	MODEL I-40	DATE/TIME IN 06.02.2023 10:55
ESS 383 SIN MING DRIVE	YR OF MANU. 17.11.2016	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMHU096364	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
UNT CARD NO.		

cident Date: 05.02.2023
TURE: 3P.05.02.23

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

lgement Slip

Exit Pass

SHD7160J JU TOKIO

Vehicle No.: SHD7160J

ervice Advisor Signature/Date

Name of Service Advisor Date

ned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:**
CTPL**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

PARTICULARS OF CLAIMClaim Type: **THIRD PARTY**

Policy No:

Vehicle Reg. No.:

Party At Fault:

SHD7160J**UNKNOWN**

Ref. No:

Date of Loss:

05/02/2023

Driveable?

YES

Make/Model:

HYUNDAI I40, 1.7 D CRDI (A)

Vehicle Colour:

BLUE

Engine No:

D4FDFU561541

Odometer:

0 KM

Vehicle Reg. Date:

17/11/2016

Gen Condition:

GOOD

Chassis No:

KMHLB41UMHU096364

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NOEst. Duration of Repair
(day)**4**

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)**COST OF CLAIMS****Amount**

Parts	1,102.72
Miscellaneous Items	11.00
Labour	650.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)**1,763.72****+ GST 8.00% (S\$)****141.10****Nett Amount (S\$)****1,904.82****This claim is handled by: JUMANI BIN MASUDIN**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 06 Feb 2023)

Parts: 143

HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD7160J/06/02/2023 14:27**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	Rv *553.00 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	nu — *22.00 FL
3	1		*REAR BUMPER MAT	0.00	0.00	X *50.00 F
4	1		*ADVERTISEMENT LOGO- BUMPER	0.00	0.00	nu — *50.00 F
5	1		*ADVERTISEMENT LOGO- FENDER	0.00	0.00	nu — *200.00 F
6	1		*RERA BUMPER BEAM	20.00	0.00	? *428.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,303.40
- List Item Discount on L Items (S\$)	200.68
Total Parts (S\$)	1,102.72

ComfortDelGro Engineering Pte Ltd/SHD7160J/06/02/2023 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280 300.00
2	SPRAYPAINT	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
Gross Labour Cost (\$\$)			650.00

ComfortDelGro Engineering Pte Ltd/SHD7160J/06/02/2023 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjin 97495744
WP 6/2/23 5pm
4/5 hours after repair
Tanjin @ 11am tomorrow
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: