

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EA123001272/4943

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS\$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MER - 00

10696.13

N/S	O/S

27/3/23 P17 & 10696.13 in hand 205001 (red & 7735.61, 42%)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-05 SUNTEC TOWER FIVE  
SINGAPORE 038985

**Registration No** : SLU6365E

**Chassis No** : JHMRC1890HC204324

**Model** : ODYSSEY 2.4 EXV-S 17YM (EURO 6)

**Owner's Name** : ONG YUU KOCK

**Ins Policy No.** : DMPG22016231

**Date of Accident** : 6/2/2023

**Document No.** : SQT23000348 **Page** 1

**Date** : 6. Feb 2023

**Customer No.** : WN004

**Svc Advisor** : YOU PO SOON

**Engine No** : K24W72041570

**Date | Time** : 6. Feb 2023 10:32:02 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: DMPG22016231 OWNER: MR ONG ACC DATE: 6/2/2023 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
60100-T6A-000ZZ	HOOD COMP <i>sent/suc</i>	1	718.70 ✓	25	539.02 ✓	43.12	582.14
80050-SP0-000	LABEL AIR CONDITIONER CAUTION <i>ner</i>	1	1.90 ✓	25	1.42 ✓	0.11	1.53
74120-T6A-003	LOCK ASSYHOOD <i>su</i>	1	113.70 X	25	85.27 X	6.82	92.09
60120-T6A-000ZZ	HINGE COMPR.HOOD <i>sent</i>	1	50.80 ✓	25	38.10 ✓	3.05	41.15
60170-T6A-000ZZ	HINGE COMPL.HOOD <i>sent</i>	1	50.80 ✓	25	38.10 ✓	3.05	41.15
60400-T6A-320ZZ	BULKHEAD COMP.FR. <i>sent</i>	1	465.10 ✓	25	348.82 ✓	27.91	376.73
80111-T6A-003	CONDENSER COMP <i>17</i>	1	729.90 X	25	547.42 X	43.79	591.21
19010-5X6-J02	RADIATOR COMP <i>17</i>	1	1442.10 X	25	1081.57 X	86.53	1168.10
04711-T6A-900ZZ	FACE,FR.BUMPER <i>27</i>	1	749.30 ✓	25	561.97 ✓	44.96	606.93
71151-T6A-911	BASE,MID GRILLE <i>cu</i>	1	205.60 ✓	25	154.20 ✓	12.34	166.54
71152-T6A-J81ZA	UPPER MOLDING,MIDDLE GRILLE <i>ere</i>	1	166.00 ✓	25	124.50 ✓	9.96	134.46
71153-T6A-J81ZA	MOLDING,MIDDLE GRILLE <i>cu</i>	1	158.90 ✓	25	119.17 ✓	9.53	128.70
71154-T6A-J81ZA	LOWER MOLDING,R.MID GR <i>cu</i>	1	42.70 ✓	25	32.02 ✓	2.56	34.58
71159-T6A-J81ZA	LOWER MOLINDG,L.MIDDLE GRILLE <i>cu</i>	1	42.70 ✓	25	32.02 ✓	2.56	34.58
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER <i>sent</i>	1	312.40 ✓	25	234.30 ✓	18.74	253.04
71193-T6A-003	SPACERR.FR.BUMPER SIDE <i>ner</i>	1	12.60 ✓	25	9.45 ✓	0.76	10.21
71198-T6A-003	SPACERL.FR.BUMPER SIDE <i>ner</i>	1	12.60 ✓	25	9.45 ✓	0.76	10.21
91505-TM8-003	CLIP,BUMPER <i>ner</i>	14	2.30 ✓	25	24.15 ✓	1.93	26.08
71121-T6A-003	BASEFR.GRILLE <i>su</i>	1	180.80 X	25	135.60 X	10.85	146.45
71122-T6A-J01	MOLDINGFR.GRILLE <i>cu</i>	1	338.20 ✓	25	253.65 ✓	20.29	273.94

Printed on 6/2/2023 6:10:21 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.





**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : ERGO INSURANCE PTE LTD  
5 TEMASEK BOULEVARD  
#04-05 SUNTEC TOWER FIVE  
SINGAPORE 038985  
**Registration No** : SLU6365E  
**Chassis No** : JHMRC1890HC204324  
**Model** : ODYSSEY 2.4 EXV-S 17YM (EURO 6)  
**Owner's Name** : ONG YUU KOCK  
**Ins Policy No.** : DMPG22016231  
**Date of Accident** : 6/2/2023

**Document No.** : SQT23000348  
**Date** : 6. Feb 2023  
**Customer No.** : WN004  
**Svc Advisor** : YOU PO SOON  
**Engine No** : K24W72041570  
**Date | Time** : 6. Feb 2023 10:32:02 AM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
75700-TA0-A00	EMBLEM.FR. <i>nel</i>	1	30.80	25	23.10	1.85	24.95
90301-ST0-003	NUT,PUSH 3MM <i>nel</i>	2	2.10	25	3.15	0.25	3.40
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED <i>one</i>	1	2516.00	25	1887.00	150.96	2037.96
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED <i>one</i>	1	2516.00	25	1887.00	150.96	2037.96
60210-T6A-300ZZ	FENDER COMPR.FR. <i>2</i>	1	587.20	25	440.40	35.23	475.63
60260-T6A-300ZZ	FENDER COMPL.FR. <i>2</i>	1	587.20	25	440.40	35.23	475.63
91512-SX0-003	CLIPINNER FENDER <i>11</i>	10	3.50	25	26.25	2.10	28.35
90682-SEA-003	CLIP ABUMPER <i>NN nel</i>	6	2.60	25	11.70	0.94	12.64
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 <i>nel</i>	6	23.20	25	104.40	8.35	112.75
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) <i>sent</i>	1	45.00		45.00	3.60	48.60
Sum Item					9238.60	739.09	9,977.69
BOSUN	SUNDRIES <i>nel</i>	1	50.00	10	50.00	4.00	54.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	160	180.00	14.40	194.40
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	8.00	108.00
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	450.00	320	450.00	36.00	486.00
BA00R	REMOVE & INSTALL FR. SENSORS.(N)	1 <i>11</i>	200.00	X	200.00	16.00	216.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	500.00	280	500.00	40.00	540.00
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	450.00	240	450.00	36.00	486.00
BKBH01R	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS <i>650</i>	1	3400.00	2600	3400.00	272.00	3672.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) <i>520 4.5</i>	1	3800.00	2340	3800.00	304.00	4104.00
Sum Labor					9130.00	730.40	9,860.40

Survey By

Date & Time

Excess

*Marcus Luk*

*7/2/23*

*Excess \$1000000 before pay*

Total Amount 18,368.60 1,469.49 19,838.09

Total (Inclusive of GST) 19,838.09

Customers hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 6/2/2023 6:10:21 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

*18431.74*



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)  
Service and Body Repair

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Tel: +65 6841 3838 Website: www.honda.com.sg  
For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-05 SUNTEC TOWER FIVE SINGAPORE 038985	<b>Document No.</b>	: SQT23000348	<b>Page</b>	3
<b>Registration No</b>	: SLU6365E	<b>Date</b>	: 6. Feb 2023		
<b>Chassis No</b>	: JHMRC1890HC204324	<b>Customer No.</b>	: WN004		
<b>Model</b>	: ODYSSEY 2.4 EXV-S 17YM (EURO 6)	<b>Svc Advisor</b>	: YOU PO SOON		
<b>Owner's Name</b>	: ONG YUU KOCK	<b>Engine No</b>	: K24W72041570		
<b>Ins Policy No.</b>	: DMPG22016231	<b>Date   Time</b>	: 6. Feb 2023 10:32:02 AM		
<b>Date of Accident</b>	: 6/2/2023	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incl GST
Status							
Signature							

Printed on 6/2/2023 6:10:21 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : ERGO INSURANCE PTE LTD  
8 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER 3  
SINGAPORE 038988

**Registration No** : SLU6365E

**Chassis No** : JHMRC1890HC204324

**Model** : ODYSSEY 2.4 EXV-S 17YM (EURO 6)

**Owner's Name** : ONG YUU KOCK

**Ins Policy No.** :

**Date of Accident** :

**Document No.** : SQT23000820 **Page** 1

**Date** : 18. Mar 2023

**Customer No.** : WN004

**Svc Advisor** :

**Engine No** : K24W72041570

**Date | Time** : 18. Mar 2023 12:54:11 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	SUPPLEMENTARY						
91578-T0A-003	CLIPFR.GRILLE	4 <i>new</i>	2.40	25	7.20	0.58	7.78
71190-T6A-003	BEAML.FR.BUMPER UPPER	1 <i>one</i>	37.30	25	27.97	2.24	30.21
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1 <i>one</i>	37.30	25	27.97	2.24	30.21
					<b>Sum Item</b>	<b>63.14</b>	<b>5.06</b>
							<b>68.20</b>

Survey By							
Date & Time				<b>Total Amount</b>	63.14	5.06	68.20
Excess				<b>Total (Inclusive of GST)</b>			<b>68.20</b>
Status							
Signature							

Printed on 18/3/2023 12:55:07 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	06/02/2023 15:01 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	06/02/2023 08:10 (SGT)
Exact Location of Accident	Woodlands, Singapore
Additional Location Information	CTE TOWADS ANG MO KIO
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU6365E
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG YUU KOCK
NRIC No	S1255211D
Email Address	YKONG07@GMAIL.COM
Mobile Phone No	(Phone) +65-97592519
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2356

#### INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	-

#### DRIVER

Name of Driver	ONG YUU KOCK
NRIC No	S1255211D
Date Of Birth	25/09/1957
Occupation	Outdoor



Date Of Driving Pass	22/04/1976
Driving experience	46 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97592519
Alt. Phone Number	-
Email Address	YKONG07@GMAIL.COM
Address	BLK 135 SERANGOON NORTH AVE 2 #10-60
Address complement	-
Postcode	550135
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED STATEMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ1514Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WANG HAO
NRIC No	S9177855F

Contact Number	(Phone) +65-85390528
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG9743P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	RHODA TONG
Contact Number	(Phone) +65-82887982
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



# SKETCH PLAN

Vehicle  
Number: SLU6365E

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The give and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing, fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature (If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

Vehicle Number: SLU6365E

SKETCH PLAN



A - SLU6365E

B - SLZ1514Z

C - SMG9743P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 6/2/2023 at about 8:10 AM, I was driving along CTE towards Ang Mo Kio.

I travel along left lane, suddenly the front car braked, and I couldn't stopped in time, and collided onto the back of the front vehicle.

This accident total involved 3 vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
(Date & Time)

Driver's Signature (if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.: