

(08/11/13) We

ASS. REC. BY:

Patan

REF:

CS/CT123001277/Rmp3

894E

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMJ 9634E*

at Workshop m/s *Volkswagen*

of *247, Alexandra Rd*

Insured: *CTI*

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) *3pm*

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *135K*

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SMJ 9634E* Yr Regn: *2022 JAN*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *SKODA OCTAVIA STYLE 1.5 TSI* c.c. *1498*

Colour: *BLACK* A/C: Insured / Std / NI / NA

Sp. Reading: *16145* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *TM BBR 7NX 4MY 179 245*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *225/45R18*

R: _____

BS / DUN / EXNOVA / GV / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *03/02/23* D.O.I. *08/02/23*

Survey held at *Volkswagen*

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 57K

Date/Time, File Pass to?

: Prell. Report
 : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1)

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) _____

Empty box for additional notes or signatures.

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
ZHANG
XIAOTONG
BLK 138A YUAN CHING ROAD
#17-115
SINGAPORE 611138

Document no.
Document date 06-02-2023
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2023003349/ 1
Job order date 06-02-2023
Service Advisor Dass Anthonidas
Christopher

License plate SMJ9634E	Model code NX34JDS1	First registration 07-01-2022	VIN TMBBR7NX4MY17945	Model OCTAVIA M-HEVSTY TS110/1.5A7F	Mileage 20
---------------------------	------------------------	----------------------------------	-------------------------	--	---------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES REPAIR				#6	280.00 X	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00 ✓	518.40
5E6807421	Rear Bumper <i>de</i>	1	pcs.	1,843.66	#6	1,843.66	1,991.15
5E7807441	Unbekannt - <i>low cover X</i>	1	pcs.	28.10	#6	28.10	30.35
5E7807393	Unbekannt <i>X</i>	1	pcs.	48.60	#6	48.60	52.49
5E7807394	LHR BUMPER BRACKET (SIDE) }?	1	pcs.	48.60	#6	48.60	52.49
	Guide Profile RHS						
	RHR BUMPER BRACKET (SIDE) }?						
5E6807377	Unbekannt	1	pcs.	65.94	#6	65.94	71.22
	LHR BUMPER BRACKET (OUTER) }?						
5E6807378	Guide Profile	1	pcs.	65.94	#6	65.94	71.22
	RHR BUMPER BRACKET (OUTER) }?						
5E6807863	Unbekannt	1	pcs.	84.22	#6	84.22	90.96
	RR BUMPER BRACKET (CTR) ?						
5E3807305D	Unbekannt	1	pcs.	625.49	#6	625.49	675.53
	REINFORCEMNT }?						
D 180KU2A1	2k-Plastic Adhesive <i>m</i>	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic <i>m</i>	1	pcs.	74.37	#6	74.37	80.32
5WA919275B GRU	Sensor Primed ?	4	pcs.	194.63	#6	778.52	840.80
3Q0919133 9B9	Seal Ring Satin Black <i>?</i>	4	pcs.	6.10	#6	24.40	26.35
5E7919485A	Sensor Bracket <i>m</i>	1	pcs.	18.66	#6	18.66	20.15
5E6919485	Sensor Bracket <i>m</i>	1	pcs.	18.66	#6	18.66	20.15
5E6919486	Sensor Bracket <i>m</i>	1	pcs.	18.66	#6	18.66	20.15
5E7919486A	Sensor Bracket <i>m</i>	1	pcs.	18.66	#6	18.66	20.15
5E6807521 9B9	Unbekannt	1	pcs.	273.69	#6	273.69	295.59
	RR BUMPER LOWER SPOILER } <i>sc</i>						
	LABOUR						
	Spray Painting	3	pcs.	840.00	#6	2,520.00	2,721.60
	CHINA TAIPING DIRECT				#6	2,400.00	2,592.00
	DOA:03/02/2023						
	TP VEH NO: SJY2240K						
	SURVEY BY:						

Quotation valid till 13-02-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	9,040.81	8%	784.06	9,800.81	10,584.87
<i>Total</i>	<i>760.00</i>	<i>9,040.81</i>		<i>784.06</i>	<i>9,800.81</i>	<i>10,584.87</i>

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Ms.
ZHANG
XIAOTONG
BLK 138A YUAN CHING ROAD
#17-115
SINGAPORE 611138

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

06-02-2023
5211001170
200208384E
30001
2023003349/ 1
06-02-2023
Dass Anthonidas
Christopher

License plate SMJ9634E	Model code NX34JDS1	First registration 07-01-2022	VIN TMBBR7NX4MY179745	Model OCTAVIA M-HEVSTY TS110/1.5A7F	Mileage 20
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

Customer


Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
3 days
08/02/23 @ 1500
Reply before paint

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	894E
Vehicle Details	
Vehicle No.:	SMJ9634E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2023
Vehicle Make:	SKODA
Vehicle Model:	OCTAVIA STYLE 1.5 TSI MHEV(A) SA
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	DFY077257
Chassis No.:	TMBBR7NX4MY179745
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,649.00
Original Registration Date:	07 Jan 2022
First Registration Date:	07 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$11,509.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2032
PARF Rebate Amount:	\$8,631.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2032
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$77,700.00
COE Rebate Amount:	\$69,157.00
Total Rebate Amount:	\$77,788.00

Skoda Octavia Mild Hybrid 1.5A TSI e-TEC Style

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

CARRO

The Better Place to Buy Cars

Price	\$135,888		
Depreciation ⓘ	\$14,580 /yr View models with similar depre	Reg Date	14-Jan-2022 (8yrs 11mths 1day COE left)
Mileage	13,755 km (12.7k /yr)	Manufactured ⓘ	2021
Road Tax ⓘ	\$684 /yr	Transmission	Auto
Dereg Value ⓘ	\$77,966 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$77,700	OMV ⓘ	\$24,649
Engine Cap	1,498 cc	ARF ⓘ	\$11,509
Curb Weight ⓘ	1,461 kg	Power	110.0 kW (147 bhp)