

ASS. REC. BY: Taufik

REF: 03/CTI 23001287/Trp3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TR / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP - PRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FRT 990M Yr Regn: 1
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Super Cub c.c. _____
Colour Red A/C: Insured / Std / NI / NA
Sp. Reading _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nit / S/Rim / STD A/Rim or _____
Tyre Size: F: 70/90R17
R: 80/90R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 07/02/230 Spm
Survey held at MCS Auto
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No GIA, Repair Range: \$3000 - \$4000, 5 days</u>

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report
Date/Time, File Return to?

2) _____
Rep. Format: _____
Lump Sum / L.B. (C) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS. SI	
Photos	
Others	
TOTAL	