REF:

ASS. REC. BY: Taufik | REF: CC3/CT/23001306/Tp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMB1584K. Yr Regn: 2014, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: MAN NL 320F c.c 10518

Colour Multi A/C: Insured / Std / NI / NA

Sp.Reading 554550 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA2227 7F7002553

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 275/70R22.5

R: " " (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken

Front		Rear	
R/Bal.	8 mm	R/Bal.	8/8 mm
L/Bal.	8 mm	L/Bal.	8/8 mm
D.O.A.		D.O.I.	7/2/23.

Survey held at SMRT WL.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) _____ ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.J. (T _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Survey Fee:	
Transportation:	
S + RS. ___ SI	
Photos	
Others	
TOTAL	