

ASS. REC. BY: REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: Income
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD3589h Yr Regn: 13/10/2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ / Prime Mover /
Truck / Trailer or
Make: Hyundai 140 c.c. 1591
Colour: Blue AC: Insured / ☒ / NI / NA
Sp. Reading: Unable to start T/Radio: Insured / ☒ / NI / NA
Eng/No: _____
C/No: KmHLB41Umhu095428
Gen. Cond: Good / ☒ / Poor / Burnt
Steering: In order / ☒ / Jammed / Leaked / Burnt or
Brake: In order / ☒ / Jammed / Leaked / Burnt or
Modl: NI / S/Rim / STD / ☒ / Rim, or
Tyre Size: F: 195/60 R15
R: 195/60 R15
BS / DUN / EXNOVA / GY / FS / LIZA / VIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front Rear
R/Bal. 5 mm R/Bal. 6 mm
L/Bal. 5 mm L/Bal. 6 mm
D.O.A. 31/1/23 D.O.I. 3/2/23 4:30pm
Survey held at Comfort
Des. of Damages ☒ / ☒ / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Total Loss

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

Date/Time: 02.02.2023 15:23 Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5790543


JC NO 305544342

DMER	REGN NO: SHD3589H	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
DMER NO. 7010045	MODEL I-40	E.....1/2.....F
ESS 383 SIN MING DRIVE	YR OF MANU 13.10.2016	DATE/TIME IN 31.01.2023 09:20
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMHU095428	TARGET DATE
(R) 65508755 (O)		COMPLETION DATE/TIME:
(P)		
UNT CARD NO.		

JOB DESCRIPTION

Accident Date: 31.01.2023
NATURE: TP/3P 31.01.2023

NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

acknowledgement Slip	Exit Pass
No.: SHD3589H CHIANG	Vehicle No.: SHD3589H
Signature/Date	Name of Service Advisor
Signature/Date	Date
Returned to Service Reception upon collection	To be kept by Security Guard