VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052

Tax invoice
Preview

Page 1/2

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Mr
MANJA
HABIB
102 TAMPINES STREET 11
#02-127
Singapore 521102

Document no.	
Document date	27-03-2023
Customer no.	5211052769
Customer GST-ID	201903913C
Dealer	30001
Job order number	2023004294/ 1
Job order date	14-02-2023
Service Advisor	Dass Anthonidas Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMT7221Z	3G24JZC0	15-07-2020	WVWZZZ3CZKE135542	Passat Comfortline 1.8 I TSI 132kW DSG	54,420

Position no.	Description	Quantity	Unit	Unit price excl. GST		Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR					#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING					#6	480.00	518.40
3G0823031C	Hood SCK A/O-15/2/2023	1	pcs.	1,817.01	28.00%	#6	1,308.25	1,412.91
3G0807217K GRU	Cover For Bumper Primed	1	pcs.	1,918.02	28.00%	#6	1,380.97	1,491.45
3G0807287 9B9	License Plate Bracket Sat	1	pcs.	124.96	28.00%	#6	89.97	97.17
N 0385494	Rivet	4	pcs.	0.48	28.00%	#6	1.38	1.49
3G0807889	Guide Piece BUMPER CTR BRACKET	1	pcs.	98.67	28.00%	#6	71.04	76.72
3G0853651A BKZ	Radiator Grille Satin Bla	1	pcs.	687.72	28.00%	#6	495.16	534.77
3G0853601B DPJ	Vw Sign Black/Bright Chro	1	pcs.	106.72	28.00%	#6	76.84	82.99
3G0998493	1 Set Sensor Brackets	1	pcs.	53.33	28.00%	#6	38.40	41.47
3G0805567A	Support For Lock Carrier (SCK) AO 8/3/2023	1	pcs.	40.84	28.00%	#6	29.40	31.75
3G0121330A	Air Duct AIR GUIDE UPPER	1	pcs.	49.12	28.00%	#6	Suppl – 35.37	38.20
	LABOUR	2	pcs.	560.00		#6	1,120.00	1,209.60
	SPRAY PAINT	2	pcs.	530.00		#6	1,060.00	1,144.80
	FRT NUMBER PLATE ALLIANZ OD DOA:04/02/202 EXCESS:-NIL- SURVEY BY:MR RASUL	1	pcs.	80.00		#6	80.00	86.40

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	760.00	5,786.78	1,371.53	8%	523.74	1,371.53	6,546.78	7,070.52
Total	760.00	5,786.78	1,371.53		523.74	1,371.53	6,546.78	7,070.52

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.