

ASS. REC. BY:

REF:

TH / 23 001336/Kg

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/5 83974.20 Caber Red \$1298.60, 25%
(No Lump Sum)

Veh No:

SMN 7135X

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

Colour

M. Red

c.c

1496

Sp. Reading

40295

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BP2SAAK1101508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

6 mm

Rear

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

20/1/23

D.O.I.

9/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation

S - RS - SI

Fees

Others

Report Format:

MER-00

Lump Sum / I.B.I. (\$

3974.20

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road

Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg; samuelxie@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	20/01/2023
Vehicle Reg. No.:	SMN7135X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		
Make/Model:	MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A)	Vehicle Reg. Date:	26/08/2019
Vehicle Colour:	RED	Chassis No:	JM6BP2SAAK1101508
Engine No:	P520624891		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8 days		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not within
Preserving B4
Ex TBA
@ 3974.20 B4
Excess*

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	2,875.20
Labour	61.00
Paintwork Labour	1,500.00
Towing	0.00
	0.00
Gross Total (S\$)	4,436.20
+ GST 8.00% (S\$)	354.90
Nett Amount (S\$)	4,791.10

This claim is handled by: OI SUN PIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2023)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SMN7135X/08/02/2023 09:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	876-30 Bu	20.00	0.00	*867.30 FL	C
2	1		*FRONT BUMPER RETAINER LH	L	20.00	0.00	*20.50 FL	X
3	1		*FRONT BUMPER RETAINER RH	Di	20.00	0.00	*20.50 FL	C
4	1		*FRONT RADIATOR GRILLE	cm	20.00	0.00	*163.10 FL	C
5	1		*FRONT RADIATOR GRILLE CHROME LH	cm	20.00	0.00	*298.00 FL	—
6	1		*FRONT RADIATOR GRILLE CHROME RH	cm	20.00	0.00	*298.00 FL	—
7	1		*FRONT BONNET	1040-80 R	20.00	0.00	*1,040.80 FL	C
8	1		*FRONT BONNET RUBBER	R	20.00	0.00	*55.90 FL	X
9	1		*FRONT EMBLEM MAZDA	54-80 nd/ter	20.00	0.00	*707.90 FL	C
10	1		*FRONT NUMBER PLATE BASE	cm	20.00	0.00	*77.00 FL	—
11	1		*FRONT NUMBER PLATE W/ CASING	Bu	20.00	0.00	*45.00 FL	C

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	3,594.00
- List Item Discount on L Items (\$\$)	718.80
Total Parts (\$\$)	2,875.20

ComfortDelGro Engineering Pte Ltd/SMN7135X/08/02/2023 09:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

<u>Miscellaneous Items</u>			Amount
1	1	FRONT BUMPER CLIPS	
2	1	OD/TP Case (Insurer)	50.00
			11.00
Sub Total (S\$)			61.00

Estimates on Labour

No Particulars

<u>Labour Items</u>		Lab.Type	Amount
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	800.00
2	To putty & respray on Front damage area.	New	650.00
3	To check wiring & focus headlamp	New	50.00
Gross Labour Cost (S\$)			1,500.00

ComfortDelGro Engineering Pte Ltd/SMN7135X/08/02/2023 09:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >