

REF:

SLV232P

Veh No: ~~2455101~~ Yr Regn: 2010 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216 V GT C.C 1496

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 175455 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA2E320405-B45618.

Gen. Cond. Good / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 805/6046.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO OF

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. *Ab* mm R/Bal. *As* mm

L/Bal. 96 mm L/Bal. 96 mm

D.O.A. D.O.I. 81/01/23

\*Survey held at Xinhuas 1/1

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

\_\_\_\_\_

---

\_\_\_\_\_

---

---

---

C7.25

8702.

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: Survey Fee:

Transportation:

Site Inp	(\$	S + RS	SI
----------	-----	--------	----

Interview (4)	Photos
---------------	--------