

Our Job Ref No 305544843 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 09.02.23 Date **FINALIZATION FORM** : <u>, ____</u> Fax: LKK **BRYAN** Attn : Mr 06.02.23 Date of Accident: **SHC1994P** Vehicle Reg No. The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-**SLC6389G** INCOME The repair job shall bill 703A 2. The finalized amount shall be: Spare Parts after List discount (b) **Labour Charges** Total for Part-By-Part Repair Cost Lumpsum Repair (if applicable) (c.) \$3,400.00 20% Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost 2 working days. Estimated normal period for repairs: 3. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 4. 7 working days We confirm the estimates and Thank you for your assistance. 5. finalized amount Signature: Signature: : BRYAN Name Name : JUMANI Date Tel 62148315 : 65468156 Fax For Official Use Only Document Confirm By Remarks Amount Attached Item (Signature) Yes or No YES Rental Rate P/Day NO 2. Loss of Income Paid 3. Survey Fees LTA Search Fee 26.75/2.00 YES 5. Medical Fees (on behalf of driver, if applicable) 6 Overrun Remarks: