

RECEIVED: Tan

REF: CS/CT123001374/Twp3

ASSIGNMENT

COE 2028 out.

From: _____ Date: _____

Estimated cost: _____

☒ OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: thb

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 476K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMX223T Yr Regn: 2008, out.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard C.D. 2362

Colour: _____ A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ANM28019756

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inoper / Jammed / Leaked / Burnt or

Brake: ☒ Inoper / Jammed / Leaked / Burnt or

Modl: Nil / SL / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 9/2/23

Survey held at Sing Ahn Tee

Des. of Damages: Fire case / Fri / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Vehicle totally burnt, not economical to repair, recommended for total loss.

Date/Time, File Pass to?

☐ : Prel. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format:

Lump Sum / L.B.R. /

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Insp (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Police

Others

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSNW00232922201	Date of Loss:	19/01/2023
Vehicle Reg. No.:	SMX223T	Driveable?	
Driver Age/Info:	35 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	SEOW ZAI YONG	Contact No:	+6588828223
Driver:	SEOW ZAI YONG		
Make/Model:	TOYOTA ALPHARD, 2.4 S (A)	Vehicle Reg. Date:	24/10/2008
Vehicle Colour:	BLACK	Chassis No:	ANH208019756
Engine No:	2AZC493099		
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO POLICE		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (\$\$)	0.00

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Noted by Repairer

Tanglin 97495747
Not Authorised
Ex: tbg
9/2/23 1020
tanglin@khanh.com

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2023)

Parts: M1-MPV TOYOTA ALPHARD 2.4 S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX223T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	277A

Vehicle Details

Vehicle No.:	SMX223T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD 2.4S A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	2AZC493099
Chassis No.:	ANH208019756
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,939.00
Original Registration Date:	24 Oct 2008
First Registration Date:	24 Oct 2008
Transfer Count:	5
Actual ARF Paid:	\$37,939.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Oct 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$18,187.00
Total Rebate Amount:	\$18,187.00

The information contained herein is correct as at 06 Feb 2023

OK