1 23601401/leg REF: ASS. REC. BY:

sennerh AS	SIGNMENT
From: Date: Estimated Cost: OD_TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: at Workshop m/s Spudg of 05 Insured:	Veh No: PBJ 2519GYr Regn: 02 1 14 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailler or Make: / Long NC 750 Xc.c 745 Colour Silm AC: Insured / Std / NI / NA Sp.Reading 7805/ T/Radio: Insured / Std / NI / NA Eng/No:
Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Yeh:	C/No: JII2RC72BFEK CU1249 Gen. Cond: Good Fair Poor Burnt Steering: Inorder Jammed Leaked Burnt or Brake: Inorder Jammed Leaked Burnt or Modl: Nil S/Rim STDARim or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value:	Tyre Size: F: 120/ 707R17 R: 160/ 607R17 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PR SUMI / TOYO / YOKO or Fron! Rear R/Bal. 2 mm R/Bal. 2 mm L/Bal. 1717 D.O.A. 7/2/23 Survey held at Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Date / Time Action / Instruction PRS En repair Cost & 4-5/6	The U/C / Chassis frame / Body Structure affected due to collision.
	Sof Repair: urvey No. of Trip: Survey Fee: Transportativi Site Insp (\$) _ \$ - R\$ _ \$! Interview (\$) Fee: Tech Invs (\$) Others Weekend (\$)





T/20230207/7029

1 of 4

Report No. T/20230207/7029

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACC	IDENT	Ī
-------------------------	-------	---

Date/Time 07/02/2023	A THE PARTY OF THE	de:	Vide Report No.:		Station Diary No.:		
Informant'	s Particul	ars					
Name of In MUHAMMA		IN RAZALI	Address: 622B TAMPINES AVENUE 12 #14-45 SINGAPORE 522622				
ID Type / II NRIC NO /		'G	Contact No.: Home/Office:	Mobile: 91	544710		
Nationality: SINGAPORE CITIZEN			Email: MUHDALIFRAZALI@GMAIL.COM				
Sex: Age: Date of Birth: Type of Informant: Male 31 23/05/1991 Rider							
Race: Malay			Language: English	Institution / School Name:			
Occupation	1:		Driving Licence Information: Class:	Date of Ex	piry:		

General Informati	on of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 07/02/2023 09:00		Type of Location: Slip road
Location:					
JALAN AHMAD II	BRAHIM			*	
Weather: Clear		Road Surface: Dry	¥.	Road	d Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traff Light	ic Volume:
Type of Collision: Ambulance revers					one conveyed by ulance:

Vehicle No.	Type	Make	Model	Color	Conditio	No of
FBJ2519G	Motorcycle	HONDA	NC750XA	White		0
QX1275P	Ambulance					0

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		





2 of 4

Report No. T/20230207/7029

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Insurance						
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date		
FBJ2519G	FWD Singapore Pte. Ltd	PNMC2021- 00003649-01	21/08/2022	20/08/2023		

Details of Perso	n Involved					
Any Pedestrian In	nvolved: No					
No. of Pedestrian		Use of Pedestrian Crossing: NA				
Rider		PRODES.				
Name	MUHAMMAD ALIF BIN RAZALI			ID No.		S9117257G
Related Vehicle	FBJ2519G (Motorcycle)				ct No.	91544710
Hospital/Clinic	NIL		Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL	
Date	NIL		Date		NIL	
No. of Days granted Medical Leave NIL			Degree of	NIL		
Driver						
Name	MUHAMMAD AIDIL B	IN NGADI		ID No.		SXXX8679Z
Related Vehicle	QX1275P (Ambulance)			Contact No.		93650026
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL
Date	NIL		Date		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of		NIL	

Brief Details.

I am rider of FBJ2519G riding behind Ambulance QX1275P along Jalan Ahmad Ibrahim just before Carrier Transicold Pte Ltd building, before the overhead bridge. The ambulance missed the slip road into AYE and stopped in the middle of the road (in front of bus stop B20). I stopped too about 5m behind, to allow the ambulance to reverse and turn into slip road. However, the ambulance continued reversing and collided into me. It was a one way road and had no means to give way since the ambulance was reversing at speed. I was not able to backpedal on my motorcycle in time.

As a result, the front of wheel of my motorcycle became lodged under the ambulance rear bumper. My motorbike remained upright.. This resulted in my motorcycle fork to get damaged, spilling out hydraulic oil.

The ambulance personnel came out of the vehicle to check on me and I am unhurt. I instructed the ambulance driver to slowly move forward to release my motorcycle while i





3 of 4

Report No. T/20230207/7029

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

stayed on my motorbike and pressing on the brakes. Once freed, i pushed my motorcycle to the side.