ALS, P.E.C. BV:	
AS	SIGNMENT
pate:	_ Veh No: SLQ 1387 X Yr Regn: 2017, June
stimated Cost:	Type(M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: VO CSWagen Sports vale 1395
at Workshop m/s	Colour While A/C: Insured / Std / NI / NA
of	Sp.Reading 79267. T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Palicy No.	C/No: WVWZZZA4ZGW562940
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: lagrader / Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 275/408-
(Policy Condition)	R: 225/40R18.
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	- BST DON'T EXMOVATET PST LIZAT WINC TO HISD PIR SUMIT
`	TOYO/YOKO or
Bal. or Market Value:  Consistent?: Yes or No	R/Bal. 06 mm R/Bal 06 mm
GIA / PR Seen: Consistent? : Yes or No	mm NBal. 00 mm
est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 02/02/23.
um Sum: % 3 Val.: Yes or No	Survey held at J-Mart.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / QU	0 /
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collisio
Date / Time Action / Instruction	
·	·
mv :	
PV:	
Nett:	
ele/Time, File Pass to? : Prelli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
ate/Time, File Return to?	Transportation:
Add Fe	96: Site Insp (\$ ) 8+R8. 81
	Eliterview (% ) Photos