



Chassis No : BE641JJ10142 /

LABOUR & MISC CHARGE	
Putty and spray painting on the affected portion.	\$ 2,200.00
Panel beating - 200	300
FT = 500	
Total	\$ 2,200.00

Acknowledged by Repairer
Signature: _____
Date: _____

1rfm
13/2/23
11am
90097659