

ASS. REC BY: T. Giffen

REF: CS3 / SMR 22012306 / Tny 3

**ASSIGNMENT**

2023 Oct

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated cost: \_\_\_\_\_  
 OD / IF / VS / TP RES / OD RES / EVA / INV / MV  
 To Inspect/Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLJ4171T Yr Regn: 2008, Oct  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Allion C.C. 1496  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 239814 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: NZT 2603032962  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: 195/65R15

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$10K.  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS WP - PRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Windforce  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 9/12/22 @ 430pm  
 Survey held at Shifter Auto  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                           |
|-------------|----------------------------------------------------------------|
|             | <u>Repair Range: \$5000 - \$6000, 7 days</u>                   |
|             | <u>19/12/22 submit PRS / repair range \$5k-\$6k and 7 days</u> |
|             |                                                                |
|             |                                                                |
|             |                                                                |
|             |                                                                |
|             |                                                                |
|             |                                                                |

Date/Time, File Pass to? ☐ : Preli. Report  
 1) 19/12/22 ☐ : Final Report

Days Of Repair: 7  
 Resurvey No. of Trip: 1

Date/Time, File Return to?  
 2) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

|                       |             |
|-----------------------|-------------|
| Survey Fee: _____     | <div></div> |
| Transportation: _____ |             |
| S + RS. \$ _____      |             |
| Photos _____          |             |
| Others _____          |             |
| TOTAL _____           |             |

Rep. Format: prs  
 Lump Sum / L.B.R. / \_\_\_\_\_