

ASS. REC. BY:

REF:

C121 23001467/KV

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

Ding Auto

of

Insured:

Policy No. DMHCSNA00009932201

Claims No. SNM23D200400/C01/LEWLC

Sum Insured:

Excess:

125d

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$895k

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

8-10 days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/6/23

Final fig \$26,141.34 confirmed by email (Ref 9477 02, 26%)

Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Time, File Return to?

Days Of Repair: 8

Resurvey No. of Trip:

Survey Fee:

Add Fee:

- ☐ : Site Insp (\$
- ☐ : Interview (\$
- ☐ : Tech Invs (\$
- ☐ : Weekend (\$

Transportation

S - RS. SI

Format: Merimen

Sum / I.B.I: (\$ 26,141.34

Veh No:

SMT 5940U Yr Regn: 07, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Sany Yang Tivoli c.c 1597

Colour:

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KPT 30A 1486P 319613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

R/Bal.

3

mm

Rear

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

13/1/23

D.O.I.

22/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Estimate Report

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10, #01-20
575645

Insurer Reference:
Repairer Reference: 058034
Date calculated: 21/02/2023 6:01 PM



Full Report
Registration: SMT5940U
Printed: 21/02/2023 6:01 PM

Summary Information

Claim	Singapore (SG)	Work Provider:	China Taiping Insurance
Location:			(Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	13/01/23
Estimated Repair Time:	15	Hire Car Start:	
Actual Repair Days:	15	Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	SSANGYONG
Model:	TIVOLI/XLV (XK)
Sub Model:	BASE MODEL
Model Sheet Number:	16 10 01
Registration:	SMT5940U
VIN number:	
Odometer:	0
Model Specs	
FROM 06.2020	1597CC 1.6LTR 94KW FRONT DRIVE SHORT VERSION

Not Authorized
Refusing B4 painting
Ex 812501
Solaris

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADJUST HEADLAMPS		2.0	8.40
NO NUMBER	R + R FRONT BUMPER SUPPORT		4.0	16.80
NO NUMBER	RENEW FRONT PANEL CPL		60.0	252.00
NO NUMBER	RENEW FRONT BUMPER		10.0	42.00
	INCLUDES: BUMPER, LOWER GRILLE AND REQUIRED ATTACHED PARTS R + R.			
NO NUMBER	RENEW BONNET		7.0	29.40
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW			
NO NUMBER	RENEW L/FRT WING (FRONT BUMPER REMOVED)		9.0	37.80
	INCLUDES: L/F WING, LEFT HEADLAMP ASSY, AND REQUIRED ATTACHED PARTS R + R			
NO NUMBER	R + R RIGHT HEADLAMP		2.0	8.40
NO NUMBER	R + R R/F WING MOULDING		2.0	8.40
NO NUMBER	RENEW WINDSCREEN		16.0	67.20
	INCLUDE: R + R NECESSARY PARTS			
NO NUMBER	DETACH + REFIT HEADLINING			
NO NUMBER	R + R L/UPPER A-PILLAR TRIM		1.0	4.20
NO NUMBER	R + R R/UPPER A-PILLAR TRIM		2.0	8.40
			2.0	8.40

Code	Description	WU	Price SGD
NO NUMBER	R + R LEFT SILL MOULDING	6.0	25.20
NO NUMBER	R + R RADIATOR	6.0	25.20
NO NUMBER	R + R CONDENSER	6.0	25.20
NO NUMBER	DRAIN/REFILL AIR CONDITIONING	2.0	8.40
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	3.0	12.60
NO NUMBER	R + R AIR CLEANER CPL	3.0	12.60
NO NUMBER	R + R REAR LOWER ENGINE ROOM COVER	2.0	8.40
NO NUMBER	R + R LEFT FRONT DRIVE SHAFT CPL	6.0	25.20
NO NUMBER	RENEW L/F STEERING KNUCKLE	12.0	50.40
NO NUMBER	DIS-/ASS L/DRIVE SHAFT	3.0	12.60
NO NUMBER	R + R AND BALANCE L/F TYRE	3.0	12.60
NO NUMBER	RENEW L/F STEERING KNUCKLE	12.0	50.40
NO NUMBER	R + R AND BALANCE R/F TYRE	3.0	12.60
NO NUMBER	R + R FRONT AXLE MEMBER	15.0	63.00
1000	FRT UNDERCARRIAGE UNDERCARRIAGE		350.00*

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	19.90	199.0	835.80
Fixed Rate			350.00
Total of Labour			1,185.80

Paint

Code	Description	WU	Price SGD
	BODY DAMPER SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	21.0	
	L/F WING NEW PART PAINTING	10.0	
	FRONT PANEL CPL SURFACE PAINT	5.0	
	FRONT BUMPER NEW PART PAINT K1R	10.0	

Paint Material Per Part

Code	Description	Price SGD
0343	BODY DAMPER SURFACE PAINT	2.82
071	BONNET NEW PART PAINTING	58.03
0741	L/F WING NEW PART PAINTING	15.72
1015	FRONT PANEL CPL SURFACE PAINT	6.16
0283	FRONT BUMPER NEW PART PAINT K1R	41.53

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			50.0	
Preparation Main Work Metal		0.80	8.0	33.60
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	6.10	61.0	256.20

Material Cost - Paint
 New Part Painting
 New Part Painting - Plastic K1R
 Surface-/Blend Paint
 Material-constant Metal
 Material-constant Plastic
Total

Price SGD
 73.75
 41.53
 8.98
 18.10
 9.00
151.36

Spare Parts

prices as at 2001-01-01
Price SGD

Code	Description	Part Number	Part Source	Price SGD	
	FRONT BUMPER	78721 35001	Original	2,600.00	✓
0283	FRT BUMPER TRIM CAP	78725 35000 WAA	Original	45.00	X
0287	L/BUMPER COVER	78775 35200	Original	170.00	✓
0295	R/BUMPER COVER	78776 35200	Original	170.00	✓
0296	LWR RADIATOR GRILLE	78795 35000	Original	260.00	✓
0303	L/F OUT BUMPER BRKT	78731 35101	Original	55.00	✓
0317	R/F OUT BUMPER BRKT	78732 35101	Original	55.00	✓
0318	FRT CTR BUMPER BRKT	78797 35000	Original	90.00	?
0319	FRT BUMPER ABSORBER	78793 35000	Original	230.00	?
033	FRT BUMPER SUPPORT	57170 35012	Original	650.00	X
0340	BODY DAMPER	78740 35100	Original	250.00	?
0343	GRILLE	78770 35100	Original	580.00	✓
0410	BONNET TRIM	79461 35200	Original	150.00	X
0413	RAD GRILLE REINF	78752 35001	Original	180.00	?
0415	RAD GRILLE BADGE	78755 34311	Original	120.00	?
0431	BONNET	61011 35500	Original	1,750.00	✓
0471	LEFT BONNET HINGE	61810 35500	Original	95.00	X
0475	RIGHT BONNET HINGE	61820 35500	Original	95.00	X
0476	BONNET INSULATION	71161 35101	Original	280.00	X
0481	BONNET LOCK	71110 37901	Original	75.00	X
0493	BONNET SAFETY LATCH	71150 35500	Original	125.00	X
0494	REAR BONNET	79420 35001	Original	340.00	X
0528	MOULDING				
0561	LEFT HEADLAMP ASSY	83103 35060	Original	1,650.00	✓
0562	RIGHT HEADLAMP ASSY	83104 35060	Original	1,650.00	X
0741	L/F WING	51811 35310	Original	650.00	✓
0763	L/F WING RR MOULDING	79715 35050	Original	120.00	✓
087	L/F W-ARCH MOULDING	79510 35100	Original	250.00	✓
0841	L/F WHEELHOUSE COVER	79710 35100	Original	180.00	✓
1015	FRONT PANEL CPL	571AS 37001	Original	1,500.00	✓
1392	COWL	79410 35905	Original	350.00	X
1401	WINDSCREEN	79110 35030	Original	1,450.00	✓
1410	WINDSCREEN SEAL	79112 35000	Original	120.00	✓
1411	WINDSCREEN BOND KIT KNGKW12			0.00	
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			
1414	SPACER	79130 35001		0.00	
1423	WINDSCREEN MOULDING	79120 35000	Original	180.00	✓
1463	LAMP SENSOR	87930 21100		0.00	?
1465	RAIN SENSOR	SEE GUIDE NO. 1463			
2185	L/SILL MOULDING	79550 35150	Original	590.00	✓
4465	CONDENSER	68400 37000	Original	980.00	?
7035	L/F DRIVE SHAFT	41300 35000	Original	1,150.00	✓

Code	Description	Part Number	Part Source	Price SGD
7053	L/F LWR CONTROL ARM	44510 35000	Original	
7054	R/F LWR CONTROL ARM	44520 35000	Original	480.00 ✓
7077	L/F STRUT	44310 35420	Original	480.00 ✓
7081	L/F STEERING KNUCKLE	41210 35101	Original	480.00 ✓
7082	R/F STEERING KNUCKLE	41220 35101	Original	520.00 ✓
7091	L/F STRUT BEARING	44322 35001	Original	520.00 ✓
7143	L/F WHEEL HUB	41420 35000	Original	260.00 ✓
7201	L/FR WHEEL	41730 35000	Original	450.00 ✓
7202	R/FR WHEEL	41730 35000	Original	550.00 ✓
7227	L/FR TYRE	205/60 R 16 .. H	Original	550.00 ✓
7228	R/FR TYRE	205/60 R 16 .. H	Original	350.00 ✓
7261	FRONT STABILISER	44710 35000	Original	350.00 ✓
7277	L/F STABI LINKAGE	44750 35000	Original	350.00 ✓
7278	R/F STABI LINKAGE	44750 35000	Original	150.00 ✓
7300	POWER STEERING	46500 35310	Original	150.00 ✓
7761	RADIATOR	21310 35220	Original	2,650.00 ✓
7789	ELECTRIC FAN CPL	21320 37200	Original	1,050.00 ✓
8910	FRT AXLE CARRIER	40100 35200	Original	890.00 ✓
9645	HIGH TONE HORN	86500 37000	Original	1,850.00 ✓

i: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings	0.00
Subtotal	31,450.00
Total	31,450.00

Extras

Code	Description	Price SGD
1001	DIAGNOSE & RESETTING ECU	500.00* ✓
	Total Extras	500.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	31,450.00	31,450.00
Labour Time Base 10 WU/h		
Total 199.0 WU X 42.00 SGD/h	835.80	
Fixed Rate	350.00	
Total of Labour		1,185.80
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 61.0 WU X 42.00 SGD/h	256.20	
Material Cost	151.36	
Total Paint Including Material		407.56
Repair Cost Excludes GST		33,543.36
GST (+8.0%)		2,683.47
Repair Cost Included GST		36,226.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/01/2023 10:48 (SGT)
Reported by	Owner
Date of Accident	13/01/2023 04:05 (SGT)
Accident Location	Punggol Rd, Singapore
Additional Location Information	Sentul Crescent to Punggol Drive
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT5940U

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Leroy Leasing
Company Reg No	53415770W
Email Address	leroy_mong@hotmail.com
Mobile Phone No	(Phone) +65-85001640
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Ssangyong
Model	Tivoli
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMHCSNW00009932201

DRIVER

Name of Driver	Leroy Mong
NRIC No	S7403934J
Date Of Birth	23/01/1974
Occupation	Outdoor

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicle(s) involved in this accident (all Insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packets); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

Sentral Crescent to Punggol Drive A S 4159404
B L 9 P 051

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	770W
Vehicle Details	
Vehicle No.:	SMT5940U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Feb 2023
Vehicle Make:	SSANGYONG
Vehicle Model:	TIVOLI 1.6D STD 6AT 2WD ABS E6 FL
Primary Colour:	Blue
Manufacturing Year:	2020
Engine No.:	67391002095451
Chassis No.:	KPT30A1USLP319613
Maximum Power Output:	96.5 kW (129 bhp)
Open Market Value:	\$19,825.00
Original Registration Date:	03 Jul 2020
First Registration Date:	03 Jul 2020
Transfer Count:	0
Actual ARF Paid:	\$19,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2030
PARF Rebate Amount:	\$14,868.00
Intended COE Rebate Details	
COE Expiry Date:	02 Jul 2030
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$34,900.00
COE Rebate Amount:	\$22,048.00
Total Rebate Amount:	\$36,916.00

The information contained herein is correct as at 21 Feb 2023

OK