



Your Ref: S2M04A50

Date: 27<sup>th</sup> February 2023

Our Ref: CS3/ASM22008846/Dvp3m4-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Low Garnet

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMR 729H**

**INSURED VEHICLE: SMZ 4329K**

**ACCIDENT DATE: 30/08/2022**

We thank you for your instruction on 10/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMR 729H from Allied Auto Appraisal.
- b) Singapore Accident Statement of Vehicles SMR 729H and SMZ 4329K.
- c) Police Report of Vehicles SMR 729H.
- d) Final Repair Bill of SMR 729H from M/s D's Graffiti Concepts Pte Ltd.
- e) Colour damaged vehicle photographs of SMR 729H.

Pre-Repair Inspection Date: 08/09/2022 at M/s D's Graffiti Concepts Pte Ltd, 8 Kaki Bukit Avenue 4 #02-24 Premier @ Kaki Bukit, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMR 729H
Make & Model	: Kia Cerato 1.6(A) LX
Year of Registration	: 2019
Chassis Number	: KNAF1416MK5052128
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.