PRS Filed By: GQ

REF: CS3/ASM22008846/Dvp3-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s D'S GRAFFITI CONCEPTS

of

Insured: SMZ 4329K

Policy No. GA622817

Claims No. S2M04A5O

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $85k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMR729H Yr Regn: 18 Dec/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: KIA CERATO 1.6 c.c 1591

Colour Silver A/C: Insured / Std / NI / NA

Sp.Reading 134550 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAF1416MK5052128 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or KUMHO

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 30/8/2022 D.O.I. 08-09-2022

Survey held at W/S 4PM

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$4000 - $5000
9/9/22	Submit PRS, repair range $4,000-$5,000
24/2/23	Submit LS $6600 (Red 6000, 47%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 24/2/23-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

___S + RS___SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / LPO: