

Your Ref: MKR/404/8983/2019 jr(ld)

Date: 03<sup>rd</sup> Apr 2023

Our Ref: CS1/LAW23001501/Any3e2

**M/s Roy & Partners**

101 Cecil Street #11-09

Tong Eng Building

Singapore 069533

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKT 6392T****INSURED VEHICLE: JSG 1661****ACCIDENT DATE: 30/05/2019**

We thank you for your instruction on 03/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKT 6392T from M/s Impact Analysis Consultant.
- b) Survey report by MSIG.
- c) Final Repair Bill of SKT 6392T from M/s Team Autopro Pte Ltd.
- d) Singapore Accident Statement of Vehicles SKT 6392T and SKZ 2846X.
- e) Police Report of Vehicles SKT 6392T, JSG 1661 and SKZ 2846X
- f) Colour damaged vehicle photographs of SKT 6392T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: SKT 6392T
Make & Model	: Toyota Corolla Altis 1.6L CVT
Chassis Number	: MR053REH104534187
Year of Registration	: 2015

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.