

*Smy*

REF:

NS/INC23001510/Svp3

ASS. REC. BY:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspcd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: FZ 1022Y *Income*

Policy No. \_\_\_\_\_

Claims No. MT/1210294-001

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Secn: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *Shc 30890* Yr Regn: *1/4/19*

Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /

Truck / Trailer or

Make: *Toyota Prius* c.c. *1789*

Colour: *Blue* A/C: Insured /  Std / NI / NA

Sp. Reading: *61770* T/Radio: Insured /  Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JTDKB3FU603079848*

Gen. Cond:  Good / Fair / Poor / Burnt

Steering: In order /  Jammed / Locked / Burnt or

Brake: In order /  Jammed / Leaked / Burnt or

Modl: NII / SIR/m / STD /  R/m; or

Tyre Size: F: *195/65 R15*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *West Lake*

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. 5 mm L/Bal. 6 mm

D.O.A. 7/2/23 D.O.I. 8/2/23 12pm

Survey held at *Comfort.*

Des. of Damages: Frt  Rear  O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/2/23	Irfan confirmed LS \$2100 (Red 1996 17.48%)

Date/Time, File Pass to?  : Preli. Report

1) \_\_\_\_\_  : Final Report

Date/Time, File Return to?

2) 17/2/23-typist

Report Format: TP

Lump Sum H.B.: (\$ 2100)

Days Of Repair: 3

Resurvey No. of Trip: 1

- Add Fee:
- : Site Insp (\$ \_\_\_\_\_)
  - : Interview (\$ \_\_\_\_\_)
  - : Tech. Invs (\$ \_\_\_\_\_)
  - : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
S + RS, SI	_____
Photos	_____
Others	_____
TOTAL	_____

A member of COMFORTDELGRO

Date/Time: 08.02.2023 08:48 Page : 1

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 5819742

JC NO305544967


TOMER  VS COMFORT TRANSPORTATION PTE LTD TOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)  QUANTITY CARD NO.	REGN NO.: SHC3089P	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)07.02.2023 13:40	DATE/TIME IN
	YR OF MANU. 01.04.2019	TARGET DATE
	CHASSIS CODE JTDKB3FU603079848	COMPLETION DATE/TIME:

Accident Date: 07.02.2023  
 Accurrence: 3P 07.02.2023

JOB DESCRIPTION

/NO LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Check-out Slip

Exit Pass

Job No.: SHC3089P CHIANG

Vehicle No.: SHC3089P

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard