

REC BY: Taufik

REF:

NS/INC 23001516/Tap3

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop no/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SMB 487H Yr Regn: 2014 Sep
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: MAN A22 C.C. 10518
Colour: Multi A/C: Insured / Std / NI / NA
Sp. Reading: 487245 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WMAA22222E7 002216
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: NT / S/Rim / STD A/Rim or
Tyre Size: F: 275/70R22.5
R: (D)
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO or Fireenza
Front: _____ Rear: _____
R/Bal. 8 mm R/Bal. 8/8 mm
L/Bal. 8 mm L/Bal. 8/8 mm
D.O.A. _____ D.O.L. 7/2/23
Survey held at SMRT WL
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop: or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised final fig \$1438, 2 days. (Red \$435, 23%)

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 2
Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

TP
Lump Sum / B.R. / P 1438



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2023

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB1487H
Case Reference Number	BUS/01/23/7016
Registration Date	9/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Leong Kok San
Type of Accident	Side Swipe
Accident Date and Time	1/26/2023 6:04 PM
Accident Reported Date and Time	1/30/2023 3:29 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1487H - LEFT CENTRE PORTION SMR9594U (TP) - INSURED WITH NTUC
Prepared Date and Time	2/7/2023 4:10 PM
Chassis Number	WMAA22ZZ2E7002216
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$200.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,873.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	07/02/2023 4:20 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Tarjim 97495419
WP 7/2/23 @ 3:15pm
2 days
Resurvey after repair
tarjim @ lkkauto. com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2023

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope	Quotation from AR				Adjusted by Surveyor, if applicable				
TO REPAIR LH PORTION	\$795.00								
Total Labour	\$795.00				530				

Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC				Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00				708				
Total Spray Painting & Panel Beating	\$878.00								

Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC				Adjusted by Surveyor, if applicable				
Total Other Costs									

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	NA
Total					\$200.00		\$200.00		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									