RECBY: TOWAR REF. NS/IN	C 23001516/Tgp3
7	INMENT
From: Date:	Veh No: SMB1487H Yr Regn: 2014, Sey.
Estimated Cost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD 1 TO 1 WS ITP RES / OD RES / EVA / INV / MV	Truck / Traller or
To Inspect/enide No:	Make: MAN A22. c.c 10518
ei Worksind Tuls	Colour Mult A/C: Insured / Std / Ri / NA
of	Sp.Reading 487245 T/Radio: Insured   Std   NT   NA
insured:	Eng/No:
Policy No.	CINO: WMAAZZZZZEZ DOZZLL
Claims No.	Gen. Cond: 360d)/ Fair / Poor / Burnt
Sum insued: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(CiienfisRecord)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Mil) S/Rim / STD A/Rim or
	Tyre Size: F: 275/30122.5.
(Pölicy Condition)	$R: \qquad 1 \qquad 1 \qquad (D)$
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY /FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the filme of inspection.	TOYO IYOKO DI FINENZA
Ball or Market Value:	Froni Rear
IDA.C Accident Rport: Consistent? : Yes or No	R/Bal. 8 mm R/Bal 8/8 mm
GIA / PR Seen:Consistent? : Yes or No	L/Bal. 8/8 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.L. 7 2 23
Lurn Sum: % 3 Val.: Yes or No	Survey held at SWRT WL
CA / REV / REP. / 24 HRS WY / Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/ST U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	1
	ı
	- i
·	
Date/Time, File Pass 10? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) ACC For	
	Faoice ) Faoice
Report France (1 Fr (1/0	filtech true (\$ ) some
Lump Sum / LEJ: (7	: Westend (\$



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 07/02/2023

User ID : JeongCH

	Section A - Accident Det	alls	
Registration Number	SMB1487H		
Case Reference Number	BUS/01/23/7016		
Registration Date	9/11/2014		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	A22		
Name of Driver	Leong Kok San		
Type of Accident	Side Swipe		
Accident Date and Time	1/26/2023 6:04 PM		
Accident Reported Date and Time	1/30/2023 3:29 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC,if any	SMB1487H - LEFT CENTRE PORTIC SMR9594U (TP) - INSURED WITH N	DN TUC	
Prepared Date and Time	2/7/2023 4:10 PM		
Chassis Number	WMAA22ZZ2E7002216		
Mileage			
Work Shop			
Repair Completion Date and Time			
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable	10.10.0016
Total Labour Cost	\$795.00	\$0.00	Tarlin 97495491
Total Spray Cost	\$878.00	\$0.00	
Total Spare Part Cost	\$200.00	\$0.00	= 2/2/23 Q 315m
Total Other Cost	\$0.00	\$0.00	w III
TOTAL COST	\$1,873.00	\$0.00	o 2 days
Lump Sum Total	\$0.00	\$0.00	
Number of Repair Days	3.0		Resure after report
Prepared / Adjusted By	Jeong Choon Hwee		
ARC / Surveyor Sign Off Date	07/02/2023 4:20 PM		tarling Oldkart. wh
Signature	8	× Line	Tanfilm 97495749  Wp' 7/2/23 Q 315 pm  2 days  Resurvey after report  tanfilm Ollekanto. wh
Remarks			LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey before/after spray painting
	Section C - Quotation and Accident	Invoice Details	To display damaged part(s) during resurvey     Parts prices are subject to confirmation
Quotation Number	Invoice Nun	nber	<ul> <li>Third party survey is on a "Without Prejudice" basis</li> </ul>
Quotation Date	Invoice Date		No illegal modification(s) is allowed
Invoice Amount	Prepared Da	ate	<ul> <li>Supplementary item(s) must be resurveyed and</li> </ul>
			is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 07/02/2023

User ID : JeongCH

			Sec	tion D - Deta	ils of Repair E	stimates	THE RESERVEN		
Part 1 - Labor	ır Works	<b>阿尔泽森</b> 韦							
Job Scope	b Scope			Quotation from AR			Adjusted by Surveyor, if applicable		
TO REPAIR LH PORTION			\$795.00						
Jotal Labour			\$795.00				530		
Part 2 - Spray	/ Painting & P	anel Beating Rela	ted Works			Table 1	La come	1.000	
Job Scope				Quotation fr	Quotation from ARC			Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00			708			
Total Spray Painting & Panel Beating			\$878.00						
Part 3 - Other	Costs - Acci	dent and Accident	Repair Related Expe	nse				THE STATE OF THE S	
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Total Other Co	sts								
Part 4 - Spare	Parts / Mater	rial Usage			1000000				
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	ner/
Total					\$200.00		\$200.00		
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
	STATE OF STATE OF	ACCEPTANCE OF THE PARTY OF THE			L. Company	No. of the second second			